AUDI E-TRON

Vehicle information


Make:	**AUDI**	License:	**2CWF587**
Gearbox:		Body color:	
Model:	**E-TRON**	VIN:	**WAUZZZGE4PB022386**
Fuel type:		Power:	**300 kW**
Version:	**BEV 95KWH 55 QUATTRO S-LINE**	First registration	**20/12/2022**
Mileage:	**139572 km**	N° of doors:	

Damage summary


Front	2
Interior	1
Left	2
Rear	1
Right	3
Roof & others	1

Commercial pictures


































Options according to the inspector

GPS	**Yes**

Tyres

Front Left

Summer

265/45/21/108/Y

Hankook

4.0 mm

Front Right

Summer

265/45/21/108/Y

Hankook

4.0 mm

Rear Left

Summer

265/45/21/108/Y

Hankook

3.0 mm

Rear Right

Summer

265/45/21/108/Y

Hankook

3.0 mm

Checks

Battery level	**30**	Category	**Passenger Car**
Certificate of Conformity	**Yes**	Compressor	**Yes**
Maintenance	**OK**	Maintenance	**10500.0**
Number of charging cables (normal)	**0**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**No**	Repair kit	**Yes**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Statutory inspection	**OK**
Statutory inspection	**20/12/2026**	Type of Maintenance book	**Digital maintenance**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.