# APPRAISAL REPORT



## IDENTIFICATION VEHICLE

| | |
|---|---|
| **Driver name:** | HM Tongeren |
| **Make:** | AUDI |
| **Model / version:** | Q3 |
| **Vin:** | WAUZZZF34P1018473 |
| **Plate:** | 2CKP200 |
| **Mileage:** | 86582 |
| **SOH:** | |
| **First registration:** | 25/08/2022 |
| **Color:** | |

## ADDITIONAL INFORMATION






| | |
|---|---|
| **Category:** | |
| **Transmission:** | |
| **Interior color:** | |
| **Metallic paint:** | ? |
| **Type of lining:** | |
| **Board computer reset:** | ? |


## DOCUMENTS

| | |
|---|---|
| **Certificate of conformity:** | ✓ |
| **Registration certificate:** | ✓ |
| **Registration certificate 2:** | ✓ |
| **Insurance certificate:** | ✗ |
| **Maintenance book:** | |
| **Number of keys:** | 2 |
| **Original key:** | ✓ |


## PICTURES







































## VIN INFORMATION

| | | |
|---|---|---|
| Radio avec système de navigation | Transmission séquentielle | 6 rapports |
| Projecteurs à allumage automatique | Matière : alliage | Lettre repère (J) |

Diamètre avant 17
Largeur arrière 7,0
Hauteur avant 65
Indice de vitesse arrière H
Climatisation automatique
Accoudoir central arrière
Euro 6
Freins arrière à disques
Rétroviseur gauche chauffant
Rétroviseur gauche asphérique

Siège avant gauche chauffant
Volant cuir
Aide au stationnement arrière
Régulateur et limiteur de vitesse

Verrouillage centralisé à commande à distance
détecteur de pluie essuie-vitre
Prétensionneurs de ceintures avant

depuis 07.22

1395 cc (1,4 L) 110 KW (essence) / 180 KW (Total)
porte-bagages pavillon noir

Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 65
Largeur avant 215
Climatisation réfrigérant 1234YF
Ordinateur de bord
Effet perle vernissée
Rétroviseur gauche à réglage électrique
Rétroviseur droit chauffant
Rétroviseurs rabattables électriques

Sièges avant chauffants
Volant multifonction
Caméra avant
Equipement Stop & Start

Ouverture du coffre électriquement

Airbag passager
Freinage d'urgence assistée autonome (urbain)
radio avec récepteur numérique

réservoir à charbon actif (EVAP)

transmission hybride PHEV

Largeur avant 7,0
Diamètre arrière 17
Indice de vitesse avant H
Largeur arrière 215
Accoudoir central avant
Garniture de pavillon Anthracite
Freins avant à disques
Rétroviseur droit à réglage électrique
Rétroviseur droit convexe
Rétroviseur intérieur jour/nuit automatique

Garnitures cuir et simili-cuir
Aide au stationnement avant
Caméra arrière de recul
Affichage lecture des panneaux de signalisation

Appel de secours

Airbag passager désactivable
Avertisseur d'angle mort

câble de charge pour station de recharge publique Mode 3 Type 2 3 (16A)
Audi Drive Select

## EQUIPMENT

| | | | |
|---|---|---|---|
| **Board computer:** | ? | **Central locking:** | ? |
| **Compressor:** | ✓ | **Cruise control:** | ? |
| **Gps:** | ? | **Power steering:** | ? |
| **Rear parking sensor:** | ? | **Repair kit:** | ✓ |
| **Front seats heated:** | ? | **Steering wheel:** | ? |
| **Electric windows:** | ? | **Climate control type:** | |
| **Headlighting type:** | | **Tow bar type:** | |
| **Charging cables:** | 0 | **Fast charging cables:** | 1 |

## TIRES

| Position | Depth | Brand | Dimensions | Type | Rims | Runflat |
|---|---|---|---|---|---|---|
| Front left | 5 mm | | 215/65R17 99V | Summer | | ? |
| Front right | 5 mm | | 215/65R17 99V | Summer | | ? |
| Rear left | 5 mm | | 215/65R17 99V | Summer | | ? |
| Rear right | 5 mm | | 215/65R17 99V | Summer | | ? |

## DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

| # | Location | Damage type |
|---|---|---|
| 1 | Interior - Chemische reiniging | Dirty |
| 2 | Contact key - Boordcomputer resetten | Not original part |
| 3 | Bumper F | Grooved |
| 5 | Alloy rim FL | Grooved |
| 6 | Outside rear-view mirror housing L | |
| 7 | Inner door sill RL - 2X | |
| 8 | Alloy rim RL | Grooved |
| 9 | Bumper R | Grooved |

| # | Location | Damage type |
|---|---|---|
| 10 | Tailgate / Boot | Dent(s) and scratch(es) |

**Total: 9**

### ACCEPTABLE / NOT TO BE INVOICED

| # | Location | Damage type | Renta® | Repaired | Already invoiced |
|---|---|---|---|---|---|
| 4 | Bodywork | Dent(s) and scratch(es) | ✓ | ✗ | ✗ |


**Total: 1**

## DAMAGES DETAILS

**1** - Interior - Chemische reiniging - Dirty








**2** - Contact key - Boordcomputer resetten - Not original part






**3** - Bumper F - Grooved









**5** - Alloy rim FL - Grooved

**6** - Outside rear-view mirror housing L




**7** - Inner door sill RL - 2X





**8** - Alloy rim RL - Grooved




**9** - Bumper R - Grooved







**10** - Tailgate / Boot - Dent(s) and scratch(es)





**4** - Bodywork - Dent(s) and scratch(es) - Renta®








## SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

**Expert**

16/10/2026 13:26