MACADAM








RENAULT EXPRESS: 5910-MFN

Vinnumber:	**VF1RJK00X70135852**	Versionname:	**Confort 1.5 Blue dCi 55 kW (75 cv) furgón derivado de turismo 55kW 4P manual**
First Registrationdate:	**17/03/2023**	Fiscalpower:	
Expertise Mileage:	**53877**	Power Kw:	
Bodytype:	**Transporter**	Body colour	**White**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Steel**
Transmission:			
Fueltype:	**Diesel**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**No**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of climate control	**Manual climate control**		

Tyres

Summer tyres:	**185/65/15/88 T**			
	Fr.L.	**Goodyear: 4 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Goodyear: 6 mm**	Re.R.	**Goodyear: 6 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**185/65 R 15 88 T**
Tyre size FR	**185/65 R 15 88 T**
Tyre size RL	**185/65 R 15 88 T**
Tyre size RR	**185/65 R 15 88 T**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Registration document, Missing, Repair/replace (lump sum)





Ignition key, Missing, Repair/replace (lump sum)




Interior, Dirty, Cleaning




Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Paint




Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)




Windscreen, Stone chip(s), Replace




Headlight R, Broken, Replace




Wheel bolt cover FR, Missing, Replace




Sliding door R, Scratch(es), Polish




Rear light R, Scratch(es), Acceptable




Wheel arch cover FR, Broken, Replace




Rear panel, Dent(s) and scratch(es), Repair and paint (complete)





Bumper R, Dent(s) and scratch(es), Repair and paint (complete)





Boot door panel RR, Dent(s), Acceptable




Boot door panel RL, Dent(s), Paintless dent repair




Tyres, No damage, Check










ALPHABET

Datos del vehículo

Marca	RENAULT	Matrícula	5910-MFN
Modelo	Express	VIN	VF1RJK00X70135852
Versión	Confort 1.5 Blue dCi 55 kW (75 cv) furgón derivado de turismo 55kW 4P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
28/06/2023	Alineado, Sustitución	13902	NEUMATICOS ARTURO BOMBA S.L.
14/08/2023	varios	19944	MARCESA SERVICIOS S.A.
01/02/2024	Sustitución	24806	JUAN QUINTANA, S.L.
11/07/2024	Rev. 30.000 kms	30005	TALLERES ORANTOS E HIJOS S.A.
07/04/2025	Ecotasa - N2, Goodyear / 185/65R15 88T EFFIGRIP COMPACT 2, Sustitucion y kit de montaje	37242	JUAN QUINTANA S.L.
12/09/2025	Luna parabrisas	43221	RALARSA HOLDING S.L.
21/01/2026	Aceite motor - - - APL 13, Arandela / tapón cárter, Filtro aceite, Prueba funcional, Serv inspección 30000 KM, Sustituir Prueba funcional, Tasa de gestión de aceites usados, Verificar Diagnosis	46586	MARCESA SERVICIOS, S.A. (MERIDA)
15/07/2026	Importe de pago por uso, Jgo escobillas limpia - BOSCH - Rec.Plat. EuroTaller, Lámpara faro dr - H7LL 58W - Nueva, Sustituir Escobillas limpiaparabrisas, Sustituir Lámpara faro dr	51736	TALLERES ORANTOS E HIJOS S.A.

Fecha	Descripción	Kilómetros	Taller