MACADAM










BMW 320: GDL24S

Vinnumber:	**WBA41FY020FT53355**	Versionname:	**320eA 150kW PHEV Touring**
First Registrationdate:	**12/07/2024**	Fiscalpower:	
Expertise Mileage:	**44096**	Power Kw:	**120**
Bodytype:		Body colour	**Skyscraper Grau metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Hybrid Petrol**	Parking lot	**624**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS			
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 50 / 17 / 98 / V / Aluminium	5,5 mm	Vredestein	Winter
	Right	225 / 50 / 17 / 98 / V / Aluminium	5,2 mm	Vredestein	Winter
Rear	Left	225 / 50 / 17 / 98 / V / Aluminium	4,7 mm	Vredestein	Winter
	Right	225 / 50 / 17 / 98 / V / Aluminium	4,5 mm	Vredestein	Winter

Assistance equipment

Number of charging cables (rapid charge)	**1**

Interior, Dirty, Chemical cleaning






Door FL, Dent(s), Repair and paint (complete)




Wing FL, Scratch(es), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (complete)






Bumper moulding FR, Scratch(es), Replace and paint




Wing RR, Repaired, Check




Door FR, Repaired, Check




Door RR, Scratch(es), Repair and paint (complete)





Wing FR, Scratch(es), Repair and paint (complete)




Bumper R, Deformed / Strained, Replace and paint




Bodywork, Paint measurement, Check



Onderhoudshistorie van: WBA41FY020FT53355

ALPHABET

Kenteken	GDL24S
Merk Model	BMW 320eA 150kW PHEV Touring
Brandstofsoort	Benzine
Datum deel1	7/12/24

Datum reparatie	Kilometerstand	Reparatie omschrijving
8/10/26	41,909	Parkeersensor
8/10/26	41,909	Voertuig diagnose
3/26/26	32,468	Olie service
3/26/26	32,468	Reparatie band(en)
7/24/24	58	Vervanging band