



Expertise

Protocol number: 46186803
Order No. / Reference: 26504980
Inspection date: 18 Jun 2026

Manufacturer: Volkswagen

Model: Golf Variant 2.0 TDI 4Motion SCR DSG Alltrack

VIN: WVVZZZCD2RW855809



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Golf Variant 2.0 TDI 4Motion SCR DSG Alltrack	
Vehicle Identification number	WVVZZZCD2RW855809
Mileage (Read)	104,234 km
First registration	26 Apr 2024
Number of holders	1
Next periodical technical inspection	04/2027
(Report not on hand)	
Power / Engine displacement	147 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	Dolphin grey metallic (C7Q)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	20,000 km
Last service on / at	03/2026 at 91,700 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB040950
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / COL 00633		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,110 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91W	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	205/55 R17 91W	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91H	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	205/55 R17 91H	Winter tyres on Light alloy	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R18 99M	Summer tyres on Steel	Sonstige	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Permanent all-wheel drive
- 30-color ambient lighting
- Electrically adjustable and heated exterior mirrors with memory function and passenger-side mirror lowering function.
- Chrome strip at the bottom of the side windows
- Decorative inlays "Nature Cross Brushed"
- Digital Cockpit Pro, multicolor
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster
- Driving profile selection
- Windscreen made of laminated safety glass, heat and sound insulating
- Speed limiter
- Rear window heated
- ISOFIX mounting points
- Rear headrests (3)
- Paint finish: Solid
- LED Plus headlights
- Illuminated strip between headlights and door handle recesses
- Fatigue detection
- Non-smoking version
- Emergency call service
- Package: Seat Comfort Package
- Radio: Radio "Ready 2 Discover" incl. "Streaming & Internet"
- Wheels: Tire Mobility Set
- Keyless start system without safe locking
- electromechanical power steering
- Seat belts: Three-point automatic seat belts for the outer rear seats
- Seat covers in "Alltrack" fabric
- Seats: Comfort seats in the front
- Start-stop system
- Telephone interface with inductive charging function
- Engine underguard
- Prepared for later activation: Navigation function "Discover Media" incl. "Streaming & Inter"
- Central locking without safe locking, with remote control and 2 remote folding keys
- Airbags: Front and rear head airbags, front side airbags, center airbag
- App-Connect Wireless for Apple CarPlay and Android Auto
- Exterior mirror housings and door handles in body color
- third brake light
- Car2X
- Roof rails, silver anodized
- Diesel particulate filter and SCR catalyst
- Parking assistance
- Electronic parking brake including auto-hold function
- Automatic headlight control, with LED daytime running lights
- Electric windows, front and rear
- Pedestrian protection measures expanded
- luggage compartment cover
- Transmission: 7-speed DSG
- Rear window wiper with intermittent function
- "Climatronic" air conditioning system
- Front headrests
- LED reading lights at the front (2) and 2 at the rear
- LED taillights
- Steering wheel: Multifunction leather steering wheel with paddle shifters
- Fog lights with cornering lights
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Brushed stainless steel pedals
- Tire pressure monitoring system (passive)
- Wheels: Alloy wheels (4) "Ronda" 7 J x 17
- Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Lane keeping assistant "Lane Assist"
- 12-volt power outlet in the luggage compartment
- Textile floor mats front and rear
- Ambient lighting with logo projection
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear



Extra equipment

- Engine underbody protection including stone chip protection
- Fire extinguisher
- IQ.LIGHT - LED matrix headlights, including Light and Sight package (Dynamic Light Assist high beam control for LED matrix headlights - Automatically dimming interior mirror - IQ.LIGHT - LED matrix headlights with LED daytime running lights, cornering lights and dynamic turn signals - LED taillights with dynamic turn signals - Dynamic headlight range control with dynamic cornering lights - Multifunction camera - Rain sensor)
- Package: Comfort package including front center airbag (electrically adjustable, folding, and heated exterior mirrors with memory function and passenger-side mirror lowering function - anti-theft alarm system with interior monitoring, backup horn and tow-away protection - front and rear head and side airbags, center airbag - "Park Assist" parking assistant including parking aid - proactive occupant protection system in conjunction with "Front Assist" and "Side Assist" - keyless locking and starting system "Keyless Access", with safe locking function)
- Package: Winter "Premium" (DSG) (Air Care Climatronic air conditioning with active combination filter, rear controls and 3-zone temperature control - leather multifunction steering wheel, heated, with shift paddles - automatically heated front windscreen washer nozzles - auxiliary heating and ventilation with remote control and timer - heated front seats and outer rear seats)
- Paint finish: Metallic
- Towbar, foldable with electric release
- Lane change assistant "Side Assist", parking assistant and exit warning (alerts the driver with visual signals in the respective exterior mirror to vehicles that could pose a danger when changing lanes - Parking assistant: monitors the area behind and beside the vehicle when reversing out of a parking space, issues visual and acoustic warning signals if a vehicle is detected crossing the parking space path, can initiate emergency braking to reduce the severity of a collision or to prevent a collision altogether)
- Navigation system "Discover Pro" incl. "Streaming & Internet" (6+1 speakers - App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Navigation system "Discover Pro" incl. "Streaming & Internet" - Radio - Voice control - Traffic sign recognition)
- Package: Business Premium incl. navigation system (DSG) (6+1 speakers, App-Connect incl. App-Connect Wireless for Apple CarPlay, Android Auto, automatic distance control, adaptive cruise control (ACC) stop/go, speed limiter, emergency brake, pedestrian detection, travel assist, lane assist, emergency assist, leather multifunction steering wheel, heated, with shift paddles, multifunction camera, Discover Media navigation incl. streaming & internet (MP3, touchscreen, USB), cargo net partition, radio, heated windshield washer system, voice control, telephone interface, Comfort with inductive charging, textile floor mats, traffic sign recognition, heated front seats)
- Park Assist system including parking aid
- Rear View reversing camera
- Wheels: Spare wheel, weight and space saving (on-board tools and jack - instead of Tire Mobility Set)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.



Value reducing factors

No.	Component group	Description
1	Trim / covers	Brightware / decorative strip (Frontscheibe rechts) - Scratched - Replace
2	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
3	Door - front right side	Door - Scratch(es) - Smart repair
4	Boot lid / rear door	Seal - Damaged - Replace
5	Electronic systems	Electronic systems (Proaktiver Insassenschutz + Side Assist + Ausparkassist) - Specify findings - Perform diagnosis
6	Trim / covers	Boot lining - Scratched - Loss in value
7	Bonnet	Bonnet - dent(s) - Repair and paint
8	Roof	Roof (Scheibe nicht fachgerecht getauscht) - Paint defect - Repair and paint

Wear and tear

No.	Component group	Description
1	2nd wheel set	2 tyres (Kein Bestandteil der Ausstattungsliste) - Does not meet the leasing specifications - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Fire extinguisher

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Damage 1: Trim / covers: Brightware / decorative strip (Frontscheibe rechts) - Scratched - Replace



Damage 1: Trim / covers: Brightware / decorative strip (Frontscheibe rechts) - Scratched - Replace



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 2: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 4: Boot lid / rear door: Seal - Damaged - Replace



Damage 4: Boot lid / rear door: Seal - Damaged - Replace




Damage 5: Electronic systems: Electronic systems (Proaktiver Insassenschutz + Side Assist + Ausparkassistent) - Specify findings - Perform diagnosis



Damage 5: Electronic systems: Electronic systems (Proaktiver Insassenschutz + Side Assist + Ausparkassistent) - Specify findings - Perform diagnosis



Damage 6: Trim / covers: Boot lining - Scratched - Loss in value



Damage 6: Trim / covers: Boot lining - Scratched - Loss in value



Damage 6: Trim / covers: Boot lining - Scratched - Loss in value



Damage 7: Bonnet: Bonnet - dent(s) - Repair and paint



Damage 7: Bonnet: Bonnet - dent(s) - Repair and paint



Damage 8: Roof: Roof (Scheibe nicht fachgerecht getauscht) - Paint defect - Repair and paint



Damage 8: Roof: Roof (Scheibe nicht fachgerecht getauscht) - Paint defect - Repair and paint



Damage 8: Roof: Roof (Scheibe nicht fachgerecht getauscht) - Paint defect - Repair and paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVVZZZCD2RW855809

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Golf Variant 2.0 TDI 4Motion SCR
DSG Alltrack

Datum	KM-Stand	Beschreibung
23.04.2026	102.959	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben vorne
12.03.2026	91.700	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsscheiben hinten; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Ölwechsel - Hinterachse; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
08.07.2025	67.155	Bremse Sonstiges; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
04.12.2024	36.294	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges