



Volvo XC40: L071ND

Vinnumber:	YV1XZEDVEM2576775	Versionname:	XC40 P8 Recharge 300kW AWD automaat
First Registrationdate:	25/06/2021	Fiscalpower:	
Expertise Mileage:	164877	Power Kw:	300
Bodytype:		Body colour:	Onyx Black metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	367
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	3	Lining semi-leather
GPS		Lining Alcantara
Autom climate control		Sun Roof electric
Radio multimedia		Panoramic roof
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 45 / 19 / 104 / V / Aluminium	5,9 mm	Continental	Summer
	Right	255 / 45 / 19 / 104 / V / Aluminium	5,0 mm	Continental	Summer
Rear	Left	255 / 45 / 19 / 104 / V / Aluminium	5,2 mm	Continental	Summer
	Right	255 / 45 / 19 / 104 / V / Aluminium	5,2 mm	Continental	Summer

Assistance equipment

Number of charging cables (rapid charge)	1
------------------------------------------	----------

Service, Maintenance, Execute



Interior, Dirty, Cleaning



Door FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Door RR, Bad repair, Repair and paint (complete)



Door FR, Bad repair, Repair and paint (complete)



Wing RR, Bad repair, Repair and paint (complete)



Kenteken	L071ND
Merk Model	Volvo XC40 P8 Recharge 300kW AWD automaat
Brandstofsoort	Elektrisch
Datum deel1	25-06-21

Datum reparatie	Kilometerstand	Reparatie omschrijving
18-06-25	127.976	APK
18-06-25	127.976	Onderhoudsbeurt
18-06-25	127.976	Volvo Check aandrijving
31-12-24	112.174	High Voltage lader aansluiting
31-12-24	112.174	Reparatie band(en)
28-06-24	95.039	Onderhoudsbeurt
28-06-24	95.039	Ruitenwischerblad(en) voorzijde
28-06-24	95.039	Vervanging band
28-06-24	95.039	Volvo Check aandrijving
28-06-24	95.039	Volvo Check slijtagedelen
11-08-23	63.135	Onderhoudsbeurt
11-08-23	63.135	Volvo Check aandrijving
11-08-23	63.135	Volvo Check slijtagedelen
26-08-22	31.620	Onderhoudsbeurt
26-08-22	31.620	Ruitenwischerblad(en) voorzijde