

INSPECTION REPORT


End of contract

GENERAL INFO

File	315676
License plate	2CST518
Vehicle identification number	WBA18FU0608C85718
Dossier	2021 363 034
Make	BMW 316d 90kW Aut.
Mileage	150596
First registration	15/11/2022
client availability date	06/07/2026
inspectionDate	09/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	Y
202	Rocker Panel Right // Painting	N
210	Door Front Right // Smart Repair Small	Y
274	Bumper Front / Grid Central / Replace	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y
544	Interior / Floor Covering / Replace	N
634	Rear Left Door Interior Coating // Replace Completely	N

Damage Pictures



Roof // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Front Right // Repair-scratch



Bumper Front // Painting-scratch



Rocker Panel Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Wing Rear Left // Smart Repair Small-dent




Door Front Right // Smart Repair Small-dent



Wing Rear Right // Repair & Painting-scratch + dent




Bumper Front / Grid Central / Replace-cracked



Windshield // Repair-glass damage



Rear Left Door Interior Coating // Replace Completely-tear



Interior / Floor Covering / Replace-tear



Seat Front Left / Rear Coating / Replace-worn