



TESLA MODEL Y: [redacted]			
Vinnumber:	LRWYGCF57PC939998	Versionname:	TESLA MODEL Y RWD 347PK 5d/p AUT (MTY13)
First Registrationdate:	15/06/2023	Fiscalpower:	
Expertise Mileage:	133807	Power Kw:	220
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1510
Fueltype:	Electric		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options			
Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Type of GPS storage	HD		

Limited Technical Inspection			
Tyres			

		255/40/20/101 W		
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				6.0
Tyre size FL				255/40 R 20 101 W
Tyre size FR				255/40 R 20 101 W
Tyre size RL				255/40 R 20 101 V
Tyre size RR				255/40 R 20 101 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				264
Tyre make RR				264

Assistance equipment			
Spare wheel	No	Jack	No
Emergency spare wheel	No	Runflat	No
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Total cost ex VAT	399,09
Seat cover FL, Worn, Acceptable	0,00



Door panel FL, Scratch(es), Acceptable

0,00



Bonnet, Stone chip(s), Acceptable

0,00



Bumper F, Stone chip(s), Acceptable

0,00



Alloy rim FL, Scratch(es), Repair and paint (complete)

133,03



Wing FL, Scratch(es), Acceptable

0,00



Roof pillar L, Scratch(es), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Alloy rim RL, Scratch(es), Acceptable

0,00



Spare wheel, Missing, Check	0,00
-----------------------------	------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Alloy rim RR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------



Wing FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Roof pillar R, Scratch(es), Acceptable	0,00
--	------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Bodywork, Not original part, Acceptable

0,00

