MACADAM











BMW iX3: 2CFY119

Vinnumber:	**WBY7X41040S152477**	Versionname:	
First Registrationdate:	**19/10/2021**	Fiscalpower:	
Expertise Mileage:	**169457**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Electric**		
Maintenance	**OK**		
Maintenance	**01/05/2028**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar collapsible**
Type of headlighting	**Headlighting LED**		
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**245/45/20/103 W**			
	Fr.L.	**Bridgestone: 5 mm**	Fr.R.	**Bridgestone: 5 mm**
	Re.L.	**Pirelli: 3 mm**	Re.R.	**Pirelli: 3 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**245/45 R 20 103 W**
Tyre size FR	**245/45 R 20 103 W**
Tyre size RL	**275/40 R 20 106 W**
Tyre size RR	**275/40 R 20 106 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**264**
Tyre make RR	**264**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**1**		

Alloy rim RL polished, Scratch(es), Repair and paint (complete)











Wing RL, Scratch(es), Acceptable




Door RL, Dent(s) and scratch(es), Repair and paint (complete)






Alloy rim FL polished, Scratch(es), Repair and paint (complete)






Charging cable (normal), Missing, Check



Boot lid covering R, Scratch(es), Acceptable





Bumper R, Scratch(es), Acceptable





Alloy rim FR polished, Scratch(es), Repair and paint (complete)






Wing FR, Scratch(es), Repair and paint (complete)






Door FR, Scratch(es), Repair and paint (complete)







Outer door handle FR, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable






Alloy rim RR polished, Scratch(es), Repair and paint (complete)










Bodywork, Paint measurement, Acceptable

