

Volkswagen ID.4 BEV 204pk 77kWh Tech Trekhaak, Jul-21, 165,050 km



Memo



VIN	WVGZZZ32ZMP047618
Initial registration	01-07-2021
Initial Dutch Registration	01-07-2021
European Type Approval	e1*2018/858*00004*03
Mileage reading / hour counter reading	165,050 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	2024 kg
Doors	5
Power capacity	150 kW
Emission code / Energy label	Z
Wheelbase	277
Loading space	
Load capacity	
RDW details	
Battery capacity	77 kWh
Range	501 km
Battery health	
Charging cables type	2
AC/DC	ACDC
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Gray
Country of registration	The Netherlands
Origin	Lease

Accessories fitted to vehicles

 Tailgate electrically operated	 Cruise control	 Parking sensors rear
 Rear view camera	 Electronic Stability Program	 Parking sensors front + rear
 Adaptive cruise control	 Electric windows front	 Start immobiliser
 Adaptive power steering	 Electric windows front + rear	 Textile upholstery
 ABS	 Electric operated seats	 Removable tow hook
 Automatic air conditioning ECC	 LED lighting	 Heated front seats
 Automatic interior mirror dimmer	 Alloy rims	 Heat reflecting glass
 Bluetooth telephone connection	 Navigation	
 Central locking remote control	 Panorama roof	

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|-----------------------------|-----------------------------|-----------------------------|
| • Achteropk verkeer waarsch | • Extra getint glas | • Multimedia scherm middel |
| • AEB | • File assistent | • Multimedia-voorbereiding |
| • Alarmsysteem | • Forward Collision Warning | • Navigatiesysteem |
| • Apple CarPl./Android Auto | • Geluidsimulator | • Oplaadmogelijkheid |
| • Armsteun achter | • Geluidsisolerend glas | • Panoramadak |
| • Armsteun voor | • Grootlichtassistent | • Passagiersairbag |
| • Bagage-scheidingsnet | • Head-up display | • Rijstrooksensor met corr. |
| • Band.sp.contr.syst. | • Hill hold functie | • Rondomzicht camera |
| • Bestuurdersairbag | • Hoofd airbag(s) a. | • Ruitensproeiers verwarmb. |
| • Bluetooth telefoonvoorb. | • Hoofd airbag(s) v. | • Spraakbediening |
| • Bots herkenning+activatie | • Hoofdsteunen actief | • Stoel best. hoogte verst. |
| • Buitensp. elekt. inklapb. | • In delen neerkl. achterb. | • Stoel pass. hoogte verst. |
| • Buitensp. elektr. + geh. | • Interieur voorverwarming | • Stuurwiel verwarmd |
| • Buitensp. elektr. + verw. | • Keyless entry | • Uitwijk assistent |
| • Centrale airbag v. | • Keyless start | • Verkeersbord detectie |
| • Connected services | • LED achterlichten | • Vermoeidheids herkenning |
| • Cruise contr.adap Stop&Go | • LED dagrijverlichting | • Verstelbaar stuur |
| • DAB radio | • Lederen stuurwiel | • Verwarmde voorruit |
| • Dodehoek detectie | • Lendesteunen (verstelb.) | • Voorstoel(en) met massage |
| • Draadloze telefoonlader | • Lichtmetalen velgen 19" | • WiFi voorbereiding |
| • Elek. achterklep met sens | • Matrix LED koplampen | • Zij airbag(s) v. |
| • ESP | • Multifunctioneel stuur | |



Comments

No remarks

Vehicle state					
MOT due date	01-07-2027	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location	Wheel locks	Not present
			Owner		
					

Tyres			
Rim size	19"		
Wheel	Brand	Type	Tread depth
Front wheel left	Nexen	Summer tyre	6 mm
Front wheel right	Nexen	Summer tyre	6 mm
Rear wheel left	Nexen	Summer tyre	5 mm
Rear wheel right	Nexen	Summer tyre	5 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection			
Incident	Component		Observations
Unacceptable damage			
1		Rear door left	scratch(es)
2		Front bumper	scratch(es)
3		Rear bumper	dent(s)
4		Kofferklep	dent(s)
			

