



MINI : FM-134-LG

Vinnnumber:	WMWXR310402M41426	Versionname:	MINI MINI Cooper Edition Greenwich 136 ch BVA7 VP [3P] bva 7-136CH-7cv (bi-corps)
First Registrationdate:	18/12/2019	Fiscalpower:	
Expertise Mileage:	109519	Power Kw:	100
Bodytype:	Berline	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		
Last service correctly filled in:	Yes		

Options

Number of keys total	2	Radio	
Number keys remote	2	Sun Roof electric	
GPS big screen color		Panoramic roof	
Windows electric F		Central consol F	
Cruise Control		Headlights Xenon/LED/Laser	
Steering wheel multifunctional		Seat cover lining	
Steering wheel leather			Lining Other
Type of climate control	Manual climate control		Lining Semi-leather

Tyres

195/55/16 91 V				
Summer tyres:	Fr.L.	Other: 45%	Fr.R.	Other: 55%
	Re.L.	Other: 50%	Re.R.	Other: 50%
Tyre profile depth FL				5.2
Tyre profile depth FR				4.6
Tyre profile depth RL				4.8
Tyre profile depth RR				5.0
Tyre size FL				195/55 R 16 91 V
Tyre size FR				195/55 R 16 91 V
Tyre size RL				195/55 R 16 91 V
Tyre size RR				195/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Interior, Dirty, Chemical cleaning



Outside rear-view mirror housing L, Scratch(es), Paint



Door FL, Scratch(es), Paint



Wing RL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Luggage compartment cover, Missing, Replace



Shutter / cover R, Missing, Replace

