


2-FHV-914



2-FHV-914 · ST Line 1.0i EcoBoost 125pk M6 · 6 August 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FHV-914	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF02XXERK2RA34257
Model	Puma	Cylinder Capacity	999 ^{cm3}
Model Versions	ST Line 1.0i EcoBoost 125pk M6	Transmission Type	Handmatig geschakelde transmissie
		First Admission	16-05-2024
Body Type	5 door hatchback	Odometer	75.332 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024		
KW	92		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Electric rear windows

Electric windows front

Leather steering wheel

Navigation system

Rear parking sensors

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Previous Repairs Visible

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	4 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	2 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	4 ^{mm}	Continental	215 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	None					

Damages



Damage Part

Rightside




Damage Type

Previous Repair



Repair Type

Panelbeating & Spray



Acceptable

No



Damage Part

Reardoor - Right



Damage Type

Small dent(s)



Repair Type

Acceptable

Acceptable

Yes



Damage Part

Alloy - Right Front



Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Bumper - Front



Damage Type

Dent(s) & Scratch(es)



Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Fender - Front Left



Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Frontdoor - Left

Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Other

Damage Type

Missing

Notes

rubbers

Repair Type

Replace

Acceptable

No



Damage Part

Bumper - Rear

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Tailgate

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Interior

Damage Type

Damaged

Notes

greep koffermet
gebroken

Repair Type

Replace

Acceptable

No