MACADAM








BMW X1 (UKL): 2ECM812

Vinnumber:	**WBA11EE0805X54156**	Versionname:	**X1 (U11) sDrive 18i 1.5i 136pk/cv 5p Aut.**
First Registrationdate:	**29/08/2023**	Fiscalpower:	
Expertise Mileage:	**98912**	Power Kw:	**100**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**plus 3300 km**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**205/65/17/100 Y**			
	Fr.L.	**Hankook: 6 mm**	Fr.R.	**Hankook: 5 mm**
	Re.L.	**Hankook: 6 mm**	Re.R.	**Hankook: 5 mm**

Tyre profile depth FL	**6.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**205/65 R 17 100 Y**
Tyre size FR	**205/60 R 17 100 Y**
Tyre size RL	**205/65 R 17 100 Y**
Tyre size RR	**205/60 R 17 100 Y**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**260**
Tyre make FR	**260**
Tyre make RL	**260**
Tyre make RR	**260**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Bonnet, Scratch(es), Acceptable




Windscreen, Stone chip(s), Windscreen repair





Wing FL, Dent(s), Acceptable




Door RL, Dent(s), Paintless dent repair




Door FL, Scratch(es), Acceptable




Luggage compartment cover, Missing, Replace



Boot lid covering R, Scratch(es), Replace





Tailgate / Boot, Scratch(es), Acceptable




Wing RR, Scratch(es), Acceptable




Door RR, Scratch(es), Acceptable






Door FR, Scratch(es), Acceptable




Wing FR, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable



Onderhoudshistorie van: WBA11EE0805X54156

ALPHABET

Kenteken	2ECM812
Merk Model	BMW X1 (U11) sDrive 18i 1.5i 136pk/cv 5p Aut.
Brandstofsoort	Benzine
Datum deel1	8/29/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/3/26	92,099	BMW/MINI service standaard omvang	Uitvoeren
8/3/26	92,099	controle niveaus	Uitvoeren
8/3/26	92,099	klein materiaal	
8/3/26	92,099	remvloeistof	Vervangen
8/3/26	92,099	ruitenwisserrubber achter	Vervangen
8/3/26	92,099	ruitenwisserrubber vooraan	Vervangen
2/20/26	69,155	batterij	Vervangen
2/20/26	69,155	BMW/MINI service standaard omvang	Uitvoeren
2/20/26	69,155	BMW/MINI service voertuig-check	Uitvoeren
2/20/26	69,155	klein materiaal	
2/20/26	69,155	service luchtfilter	Uitvoeren
2/20/26	69,155	service microfilter	Uitvoeren
2/20/26	69,155	service motorolie	Uitvoeren
12/2/25	57,129	BMW/MINI service standaard omvang	Uitvoeren
12/2/25	57,129	bougie	Vervangen
12/2/25	57,129	klein materiaal	
12/2/25	57,129	remblokken vooraan	Vervangen
1/14/25	31,202	BMW/MINI service standaard omvang	Uitvoeren
1/14/25	31,202	klein materiaal	
1/14/25	31,202	service microfilter	Uitvoeren
1/14/25	31,202	service motorolie	Uitvoeren