


2-FAX-964


2-FAX-964 · 318iA Berline Business Edition · 2 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FAX-964	Fuel Type	Gasoline
Manufacturer	BMW	VIN	WBA28FF0608E17202
Model	318i	Cylinder Capacity	1.998 ^{cm³}
Model Versions	318iA Berline Business Edition	Transmission Type	Automatisch geschakelde Transmissie
Body Type	Sedan / Limousine	First Admission	11-03-2024
Color	Grey	Odometer	78.193 ^{Km}
Paint Type	Metallic	Numer Of Keys	1
Production Year	2024	Interior	Grey
KW	115	Number Headrests	5

Images





Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Rear view camera
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel - Heated

Condition

Condition exterior	Adequate	Maintenance Remarks	Olie verversen over 17000 km
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	Unknown		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Hankook	225 ^{mm}	50 ^{mm}	17 ^{inch}	Summer
Rear Left	4 ^{mm}	Hankook	225 ^{mm}	50 ^{mm}	17 ^{inch}	Summer
Front Right	6 ^{mm}	Hankook	225 ^{mm}	50 ^{mm}	17 ^{inch}	Summer
Rear Right	4 ^{mm}	Hankook	225 ^{mm}	50 ^{mm}	17 ^{inch}	Summer
Spare Tire Type		None				

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Sleutel	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Door-edge chipped	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Left	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	small dents / small scratches	Panelbeating & Spray	No



Damage Part
Alloy - Right Front

Damage Type
Damaged

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Reardoor - Right

Damage Type
Small scratch(es)

Repair Type
Polish

Acceptable
No



Damage Part
Fender - Rear Right

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No