



Audi A6 (MKL): 2ANR740

Vinnumber:	WAUZZZF28MN090448	Versionname:	A6 Avant Business Edition 35 2.0TDi 163pk/cv 5p S-Tronic
First Registrationdate:	27/05/2021	Fiscalpower:	
Expertise Mileage:	100726	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Diesel		
Maintenance	OK		
Maintenance	12500.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/18/102 Y			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.
	Re.L.	Bridgestone: 5 mm	Re.R.
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			225/55 R 18 102 Y
Tyre size FR			225/55 R 18 102 Y
Tyre size RL			225/55 R 18 102 Y
Tyre size RR			225/55 R 18 102 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			264
Tyre make FR			264
Tyre make RL			255
Tyre make RR			255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper F, Scratch(es), Spot repair





Headlight L, Scratch(es), Polish



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Polish



Wing RL, Scratch(es), Polish



Charging cable (normal), Missing, Check



Charging cable (fast), Missing, Check



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Replace



Tailgate / Boot, Scratch(es), Acceptable



Wing RR, Scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Kenteken	2ANR740
Merk Model	Audi A6 Avant Business Edition 35 2.0TDi 163pk/cv 5p S-Tronic
Brandstofsoort	Diesel
Datum deel1	5/27/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/18/26	98,000	Tussentijdse onderhoudsbeurt (variabel	Uitvoeren
8/29/24	62,730	brandstof hoofdfilter	Vervangen
8/29/24	62,730	klein materiaal	Uitvoeren
8/29/24	62,730	koelwatervloeistof	Bijvullen/-laden
8/29/24	62,730	luchtfiler interieur	Vervangen
8/29/24	62,730	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
8/29/24	62,730	remvloeistof	Vervangen
8/29/24	62,730	ruitenswisserrubber achter	Vervangen
8/29/24	62,730	ruitenswisserrubber vooraan	Vervangen
8/29/24	62,730	ruitenswisservloeistof	Bijvullen/-laden
8/29/24	62,730	versnellingsbakolie	Uitvoeren
2/17/23	32,189	klein materiaal	Uitvoeren
2/17/23	32,189	koelwatervloeistof	Bijvullen/-laden
2/17/23	32,189	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
2/17/23	32,189	ruitenswisserrubber achter	Vervangen
2/17/23	32,189	ruitenswisservloeistof	Bijvullen/-laden