DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	ZAC5JABL6 RJK77081	Registration date	18/07/2024	Exterior Color	Inconnu
Brand	JEEP	Licence Plate	WI-M 525	Odometer	45 834 km
Model	AVENGER 1.2 GSE T3 GDI Longitude				

Inspection Details

Arrival Date	13/08/2026	Inspection ID	7115299	Inspection date	13/08/2026
Assign Date	13/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys AKB Kitzingen






















Generic equipment

Removable element

Rear parcel shelf	✔
Spare wheel kit	✖

Technical Document

User manual	✔
Warranty booklet	✔
Log books	✔
Spare key	✔
Key	✔
Remote key	✔
Service	✔

Tyres

Bridgestone 215/65/16 H Summer 6.0 mm

Bridgestone 215/65/16 H Summer 6.0 mm



Bridgestone 215/65/16 H Summer 4.0 mm

Bridgestone 215/65/16 H Summer 4.0 mm

Exception / Damage

DEKRA

DEKRA Automotive Solutions

Appraisal Report

1



Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

2



Part	Bonnet	Repair Time	0.90	Part Cost	-
Position	-	Repair Cost	126.00€	Gross Cost	456.00€
Damages	Chemical deposit	Paint Time	2.20	Depreciation %	15.00%
Severity	-	Paint cost	330.00€	Depreciation	- 68.40
Repair mode	Repair	Flat Rate	-	**Net Cost**	**387.60€**

3



Part	Windscreen	Repair Time	3.20	Part Cost	711.22€
Position	Front	Repair Cost	448.00€	Gross Cost	1,159.22€
Damages	Broken	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**1,159.22€**

4



Part	Fixing glue kit	Repair Time	-	Part Cost	61.51€
Position	Front	Repair Cost	-	Gross Cost	61.51€
Damages	Broken	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 9.23
Repair mode	Replace	Flat Rate	-	**Net Cost**	**52.28€**

5



Part	Door	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	-
Damages	Not conform	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

6



Part	Door	Repair Time	-	Part Cost	-
Position	Back left	Repair Cost	-	Gross Cost	-
Damages	Not conform	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

7



Part	Wing	Repair Time	1.80	Part Cost	-
Position	Back left	Repair Cost	252.00€	Gross Cost	417.00€
Damages	Dent & Chips	Paint Time	1.10	Depreciation %	15.00%
Severity	-	Paint cost	165.00€	Depreciation	- 62.55
Repair mode	Repair	Flat Rate	-	**Net Cost**	**354.45€**

8



Part	Tailgate / Boot door	Repair Time	0.80	Part Cost	-
Position	Back	Repair Cost	112.00€	Gross Cost	112.00€
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Smart Repair	Flat Rate	112.00€	**Net Cost**	**112.00€**

9



Part	Wing	Repair Time	1.60	Part Cost	-
Position	Back right	Repair Cost	224.00€	Gross Cost	389.00€
Damages	Dent & Chips	Paint Time	1.10	Depreciation %	15.00%
Severity	-	Paint cost	165.00€	Depreciation	- 58.35
Repair mode	Repair	Flat Rate	-	**Net Cost**	**330.65€**

10



Part	Door	Repair Time	-	Part Cost	-
Position	Back right	Repair Cost	-	Gross Cost	-
Damages	Not conform	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

11



Part	Door	Repair Time	-	Part Cost	-
Position	Front right	Repair Cost	-	Gross Cost	-
Damages	Not conform	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

12



Part	Spare wheel kit	Repair Time	0.10	Part Cost	112.93€
Position	-	Repair Cost	14.00€	Gross Cost	126.93€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**126.93€**

13



Part	Bonnet badge	Repair Time	-	Part Cost	36.00€
Position	Front	Repair Cost	-	Gross Cost	36.00€
Damages	Broken	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 5.40
Repair mode	Replace	Flat Rate	-	**Net Cost**	**30.60€**

14



Part	Rear parcel shelf retaining strap hook	Repair Time	0.30	Part Cost	153.51€
		Repair Cost	42.00€	Gross Cost	195.51€
Position	Back left	Paint Time	-	Depreciation %	15.00%
Damages	Missing	Paint cost	-	Depreciation	- 29.33
Severity	-	Flat Rate	-	**Net Cost**	**166.18€**
Repair mode	Replace				

15

Part	Paint preparation	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	255.00€
Damages	-	Paint Time	1.70	Depreciation %	15.00%
Severity	-	Paint cost	255.00€	Depreciation	- 38.25
Repair mode	Paintworks	Flat Rate	-	**Net Cost**	**216.75€**

Summary Inspection

Gross Price	3,208.17€	Depreciation	-271.51€	Net Price	2,936.66€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	8.70	1,218.00€	7.93 %	-96.60€	1,121.40€
Paintwork	150.00€	4.40	660.00€	15.00 %	-99.00€	561.00€
Paint preparation	150.00€	1.70	255.00€	15.00 %	-38.25€	216.75€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	1,075.17€	3.50 %	-37.65€	1,037.52€
Flat Rate	-322.44€	-	-	-322.44€