

BYD

BYD SEAL U DM-I DESIGN

VIN: LGXCD4C44R0010862



Description

Registration number	Registration date	Odometer
-	-	33095 km
Color	Year	Upholstery
-	2024	-
Number of doors	Number of seats	Generation
-	-	-

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok	Engine start issue	✓ No

Defects & corrections

#	Element	Defect	Correction
001	Ac discharge / -	Missing	Replace
002	Bumper / Front	Scratched	Repair



003	Spoiler / Front	Scratched	Repair
			
004	Bumper / Back	Scratched	Repair
			
005	Spoiler / Back	Scratched	Repair
			
006	Door / Back Right	Chip	Repair
			
007	Registration plates / Front	Broken	Replace
			

Main set of tyres

Front Left	MICHELIN	235 / 50 / 19 / Summer	5 mm
Front Right	MICHELIN	235 / 50 / 19 / Summer	5 mm
Back Left	MICHELIN	235 / 50 / 19 / Summer	7 mm
Back Right	MICHELIN	235 / 50 / 19 / Summer	7 mm

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer




Navigation



Cable




Vin



Other



Other



Other



Other



Main set of tyres / Front Left




Main set of tyres / Front Left




Main set of tyres / Front Right



Main set of tyres / Front Right



Main set of tyres / Back Left



Main set of tyres / Back Left



Main set of tyres / Back Right



Main set of tyres / Back Right




Bumper / Front / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched




Bumper / Front / Scratched



Spoiler / Front / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched




Bumper / Back / Scratched



Bumper / Back / Scratched



Spoiler / Back / Scratched



Spoiler / Back / Scratched



Spoiler / Back / Scratched



Door / Back Right / Chip



Door / Back Right / Chip



Registration plates / Front / Broken



Registration plates / Front / Broken

