



Peugeot 508 (KKL): 2AQX572

Vinnumber:	VR3F4DGZTMY513813	Versionname:	508 SW GT 1.6 PureTech Hybrid 225 180pk/cv 5p eEAT8
First Registrationdate:	16/06/2021	Fiscalpower:	
Expertise Mileage:	93031	Power Kw:	132
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Hybrid Petrol		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/45/18/98 V			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL	6.0			
Tyre profile depth FR	6.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	235/45 R 18 98 V			
Tyre size FR	235/45 R 18 98 V			
Tyre size RL	235/45 R 18 98 V			
Tyre size RR	235/45 R 18 98 V			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	259			
Tyre make FR	259			
Tyre make RL	261			
Tyre make RR	261			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	1		

Seat cover FR, Stain, Cleaning



Centre console, Scratch(es), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Dent(s), Paintless dent repair



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Tyre FL, Tear, Replace



Outside rear-view mirror housing L, Broken, Replace and paint



Door RL, Bad repair, Repair and paint (complete)



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Door FL, Repaired, Check



Wing RL, Repaired, Check



Outer sill L, Bad repair, Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Fog light RR, Crack, Replace



Bumper moulding R, Crack, Replace



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Acceptable



Door FR, Dent(s), Acceptable



Roof, Dent(s), Paintless dent repair



Kenteken	2AQX572
Merk Model	Peugeot 508 SW GT 1.6 PureTech Hybrid 225 180pk/cv 5p eEAT8
Brandstofsoort	Benzine
Datum deel1	6/16/21

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/30/26	85,107	batterij	Vervangen
10/23/24	52,000	batterij	Vervangen
8/30/24	49,881	diagnose	Uitvoeren
8/30/24	49,881	klepdeksel	Vervangen
6/25/24	44,497	oliezeef	Vervangen
6/25/24	44,497	onderhoud 3e jaar	Uitvoeren
2/16/23	21,765	oliezeef	Vervangen
2/16/23	21,765	onderhoud 1e jaar	Uitvoeren