



Expertise

Protocol number: 46396192
Order No. / Reference: 26615144
Inspection date: 8 Jul 2026

Manufacturer: Mercedes-Benz
VIN: W1N9N0CB1RJ086490

Model: EQA 250+ Electric Art



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz EQA 250+ Electric Art	
Vehicle Identification number	W1N9N0CB1RJ086490
Mileage (Read)	97,602 km
First registration	3 Aug 2023
Number of holders	1
Power / Engine displacement	95 kw /
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Nachtschwarz
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	102 Tag(e)
Last service on / at	10/2025 at 78,044 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV722899
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BEE 00013		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,470 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 103T	Summer tyres on Light alloy	Continental	3mm / 3mm
2)	235/50 R19 103T	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R18 102T	Winter tyres on Light alloy	Continental	3mm / 3mm
2)	215/60 R18 102T	Winter tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- Acoustic environmental protection
- Anti-lock braking system (ABS)
- ATTENTION ASSIST
- outdoor thermometer
- Color glass
- Third brake light in LED technology
- EASY-Pack tailgate with electric operation for opening and closing
- Chassis: Comfort chassis with lowered suspension
- Electric windows, front and rear
- Luggage net on driver and passenger seatbacks
- Transmission: Direct drive
- rear window wiper
- Climate: THERMATIC automatic climate control
- Headrests (5)
- Paint finish: Solid
- Chrome-look loading sill protector
- Charging system: Direct current charging system (DC charging)
- LED High Performance Headlights
- Mercedes-Benz emergency call system
- Navigation accessories: Extended MBUX functions
- Navigation accessories: Pre-installation for remote and navigation services
- Package: Cargo space
- Package: Seating comfort
- Radio: MBUX multimedia system
- Radio accessories: Touchpad
- Remote and Charging Services Premium
- Windscreen wipers with rain sensor
- Seats: Comfort seats
- Power outlet: 12V socket in the luggage compartment
- TIREFIT with tire inflation compressor
- Immobiliser
- Adaptive Highbeam Assist
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Lane Keeping Assist
- Ambient lighting
- Rear armrest
- Electrically adjustable exterior mirrors
- Basic services
- Double cup holder
- DYNAMIC SELECT
- Door sills with model-specific lettering, illuminated and with interchangeable cover
- Vehicle key set
- Velour floor mats in black
- Speed Limit Assistant
- Rear window heated
- Black fabric headliner
- Communication module (LTE) for the use of Mercedes me connect services
- Charging cable for wallboxes and public charging stations, 5m, smooth
- Charging system: Alternating current charging system (AC charging) up to 11 kW (3-phase)
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation: Hard disk navigation
- Package: Light and Visibility Package
- Upholstery: ARTICO man-made leather / two-tone fabric
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Rear view camera
- Seats: 4-way lumbar support for driver and front passenger
- Seats: Rear seat backrests foldable
- Cruise control
- High-visibility vest for drivers
- Central locking with remote control



Extra equipment

- Heated windshield washer system (washer hoses and spray nozzles heated by coolant waste heat - at temperatures below +5 degrees Celsius, the heating system operates in an energy-saving manner and only draws as much power as is necessary to defrost and keep the cleaning system clear - washer fluid reservoir with a capacity of 5 liters)
- Package: Advanced Plus (Fully digital instrument display, high resolution 10.25" - CENTRAL MEDIA DISPLAY 10.25" - Mirror package: interior and exterior mirrors automatically dimming, exterior mirrors electrically folding, ambient lighting for the exterior mirrors to illuminate the entry area - Parking package with reversing camera - Active Park Assist with PARKTRONIC - THERMOTRONIC automatic climate control - KEYLESS-GO Comfort package: KEYLESS-GO function, EASY-PACK tailgate - Wireless charging system for mobile devices in the front - Advanced sound system - 10 speakers, 225 W, Blind Spot Assist)
- Package: Driving Assistance (Active Distance Assist DISTRONIC - Active Speed Limit Assist - Extended Automatic Restart on Highways - Route-Based Speed Adaptation with Traffic Jam Definition - Active Steering Assist - Active Emergency Stop Assist with SOS Function - Emergency Lane Radio - Active Brake Assist - Turning and Intersection Function - Traffic Jam Emergency Braking Function - Evasive Steering Assist - Active Blind Spot Assist - Exit Warning Function - PRE-SAFE)
- Package: Night (45.7 cm (18") aerodynamically optimized 5-twin-spoke alloy wheels, painted black and polished with 235/55 R 18 tires on 7.5 J x 18 ET 53.5 rims; front and rear aprons and side panels with high-gloss black inserts; high-gloss black exterior mirror housings; high-gloss black beltline trim and window line trim; black roof rails; heat-insulating dark-tinted glass from the B-pillar; black B-pillar trim)
- Radio accessories: Burmester surround sound system (with 12 speakers and 590 watts system power)
- Smartphone integration (consisting of Apple CarPlay and Android Auto)
- Steering wheel: Multifunction sports steering wheel in Nappa leather (The multifunction sports steering wheel in Nappa leather with black control panels will delight you with every glance and every touch. The soft Nappa leather is of exquisite quality. The steering wheel thus conveys a passion for high-quality automotive details at all times.)
- Traffic Sign Assist (driver assistance system for recognizing speed limits, entry and overtaking prohibitions, and their cancellation; detection of traffic signs via multifunction camera and display in the instrument cluster in real time and comparison with navigation data; helps the driver to comply with traffic regulations, increases driving safety; wrong-way driving warning function: with corresponding signage, visual and acoustic warning signal when entering a road against the prescribed direction of travel)
- Airbag: Side airbags in the rear
- Cargo net (This feature protects you from loose items in the luggage compartment. The cargo net is very easy to use. You can attach or remove it in just a few steps.)
- Chassis: Adjustable damping (The chassis with adjustable damping offers this fascinating range. The DYNAMIC SELECT rocker switch in the center console selects the program and thus the characteristic. It's as if you had two chassis in one car – refined sportiness.)
- Decorative elements, black open-pore linden wood
- Navigation accessories: MBUX Augmented Reality for Navigation (To help you find your way in complex traffic situations, MBUX Augmented Reality for Navigation connects the virtual world with the real one. The technology overlays graphical navigation and traffic information onto live images. You reach your destination quickly, safely and stress-free.)
- Package: Connectivity Package Navigation (Hard drive navigation - pre-installation for navigation services)
- Package: ENERGIZING Package Plus (Advanced sound system with 10 speakers and 225 watts system power - Heated seats for driver and front passenger - Ambient lighting - THERMOTRONIC automatic climate control - Freshness, vitality, training: video instructions - Tips: 3-minute audio information for the sustainable promotion of health and well-being in everyday life - for the body regions head, shoulders, upper body, lower back and pelvis - Multi-contour seats for driver and front passenger with massage function - Electrically adjustable lumbar support)
- Package: MBUX Innovation Package (MBUX Interior Assistant: - 3D camera in the overhead control unit - Proximity sensors around the touchscreen and touchpad head-up display)
- Package: Parking package with 360° camera (12 ultrasonic sensors: 4 each at the front and rear and 2 on the sides in the front and rear bumpers - 360° camera: four networked cameras, display in the media display, virtual guidelines, trailer mode - PARKTRONIC parking assistant: visual and acoustic warning of detected obstacles according to distance and position, visual and acoustic warning of detected cross traffic while reversing out of a parking space, can briefly limit the approach speed)
- Seats: Driver's seat electrically adjustable with memory (the memory programming includes all seat adjustment options such as seat height and fore/aft position, seat cushion tilt and backrest tilt - exterior mirrors and the optional head-up display are also integrated - dynamic seating while driving. Small movements of the seat cushion and backrest in three programs and two speeds)
- Steering wheel: Steering wheel heating
- Steering: Direct steering
- Wheels: Complete summer wheel sets fitted at the factory
- Wheels: Winter complete wheels M+S 4-way 45.7 cm (18") light alloy wheels in 10-spoke design (black painted and gloss-turned with 215/60 R 18 on 6.5 J x 18 ET 44.5)



- Wheels: 48.3 cm (19") AMG light-alloy wheels, 4-piece set in 5-twin-spoke design (aerodynamically optimized, painted in high-gloss black and polished with 235/50 R 19 tires on 7.5 J x 19 ET 53.5 rims)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	2nd wheel set	2 tyres - Worn - Replace
2	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
3	Side panel - rear right side	Side panel - Deformed - Repair and paint
4	Door - front right side	Door - Scratch(es) - Paint
5	Door - rear right side	Door - Scratch(es) - Paint
6	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Boot lid / rear door	Boot lid - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Documents - Log book

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Damage 1: 2nd wheel set: 2 tyres - Worn - Replace




Damage 1: 2nd wheel set: 2 tyres - Worn - Replace



Damage 1: 2nd wheel set: 2 tyres - Worn - Replace




Damage 1: 2nd wheel set: 2 tyres - Worn - Replace



Damage 2: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 2: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 3: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 3: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 3: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 4: Door - front right side: Door - Scratch(es) - Paint




Damage 4: Door - front right side: Door - Scratch(es) - Paint



Damage 4: Door - front right side: Door - Scratch(es) - Paint




Damage 5: Door - rear right side: Door - Scratch(es) - Paint




Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 6: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 6: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 6: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Wear and tear 4: Boot lid / rear door: Boot lid - dent(s) - No deduction



Wear and tear 4: Boot lid / rear door: Boot lid - dent(s) - No deduction