MACADAM










## Renault Captur: L401SX

| | | | |
|---|---|---|---|
| Vinnumber: | **VF1RJB00767391775** | Versionname: | **Captur 1.3 TCE 113kW Intens EDC** |
| First Registrationdate: | **30/07/2021** | Fiscalpower: | |
| Expertise Mileage: | **155653** | Power Kw: | **113** |
| Bodytype: | | Body colour | **Two-tone Gris Highland / Noir Etoilé** |
| Gearbox: | **Automatic** | Paint type | **Metalic** |
| Transmission: | | Type of rims (mounted) | **Aluminium** |
| Fueltype: | **Petrol** | Parking lot | **526** |
| Number of seats | **5** | | |
| Type of rims (mounted) | **Aluminium** | | |
| Maintenance needed | **Yes** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **2** | Rear parking sensors | |
| GPS | | Hook | |
| Autom climate control | | | |

## Tyres

| Location | Position | Measures | Depth | Make | Type |
|---|---|---|---|---|---|
| Front | Left | 215 / 60 / 17 / 96 / H / Aluminium | 3,0 mm | Bridgestone | Summer |
| | Right | 215 / 60 / 17 / 96 / H / Aluminium | 3,0 mm | Bridgestone | Summer |
| Rear | Left | 215 / 60 / 17 / 96 / H / Aluminium | 4,0 mm | Continental | Summer |
| | Right | 215 / 60 / 17 / 96 / H / Aluminium | 4,0 mm | Continental | Summer |

## Assistance equipment

### Service, Maintenance, Execute



### Door RL, Dent(s), Repair and paint (complete)







### Wing FL, Dent(s) and scratch(es), Repair and paint (complete)







**Bumper F, Scratch(es), Repair and paint (complete)**





**Door FR, Scratch(es), Repair and paint (complete)**





**Bodywork, Scratch(es), Polish**




# Onderhoudshistorie van: VF1RJB00767391775

ALPHABET

| | |
|---|---|
| **Kenteken** | L401SX |
| **Merk Model** | Renault Captur 1.3 TCE 113kW Intens EDC |
| **Brandstofsoort** | Benzine |
| **Datum deel1** | 7/30/21 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|---|---|---|
| 4/9/26 | 138,910 | Accu |
| 4/9/26 | 138,910 | Onderhoudsbeurt |
| 4/9/26 | 138,910 | Remblokken achterzijde |
| 4/9/26 | 138,910 | Thermostaat |
| 10/1/25 | 121,128 | Bougie |
| 10/1/25 | 121,128 | Luchtfilter |
| 10/1/25 | 121,128 | Onderhoudsbeurt |
| 6/18/25 | 112,764 | APK |
| 11/21/24 | 97,908 | Onderhoudsbeurt |
| 11/21/24 | 97,908 | Ruitenwisserblad(en) achterzijde |
| 11/21/24 | 97,908 | Ruitenwisserblad(en) voorzijde |
| 10/18/24 | 94,425 | Reparatie band(en) |
| 7/26/24 | 87,836 | Luchtfilter |
| 7/26/24 | 87,836 | Onderhoudsbeurt |
| 7/26/24 | 87,836 | Remvloeistof |
| 7/26/24 | 87,836 | Sleutelbatterij |
| 9/4/23 | 67,857 | Bougie |
| 9/4/23 | 67,857 | Luchtfilter |
| 9/4/23 | 67,857 | Multiriem inclusief spanner |
| 9/4/23 | 67,857 | Onderhoudsbeurt |
| 9/4/23 | 67,857 | Remschijf + blokken voor |
| 9/4/23 | 67,857 | Ruitenwisserblad(en) voorzijde |
| 9/4/23 | 67,857 | Vervanging band |
| 9/4/23 | 67,857 | Waterpomp |
| 5/11/23 | 57,018 | Bougie |
| 5/11/23 | 57,018 | Onderhoudsbeurt |
| 3/7/23 | 51,912 | Reparatie band(en) |
| 1/2/23 | 46,868 | Vervanging band |
| 9/20/22 | 39,360 | Sleutelbatterij |
| 6/23/22 | 29,314 | Onderhoudsbeurt |