



Expertise

Protocol number: 46842820
Order No. / Reference: 26636319
Inspection date: 30 Jul 2026

Manufacturer: Mercedes-Benz
VIN: W1K5M8HB2TN595283

Model: CLA 200 Shooting Brake 7G-DCT Edition AMG Line



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz CLA 200 Shooting Brake 7G-DCT Edition AMG Line	
Vehicle Identification number	W1K5M8HB2TN595283
Mileage (Read)	10,726 km
First registration	25 Sept 2025
Number of holders	1
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,332 ccm / 4
Power	120 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	MANUFAKTUR Lack MANUFAKTUR alpingrau uni
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	65 Tag(e)
Key is / should be	2 / 2	FZG documents	Registration and title documents unavailable
		Letter No.	HQ402400
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BON 00042		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,050 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R19 93W	Summer tyres on Light alloy	Bridgestone	7mm / 7mm
2)	225/40 R19 93W	Summer tyres on Light alloy	Bridgestone	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 91H	Winter tyres on Light alloy	Bridgestone	7mm / 7mm
2)	225/45 R18 91H	Winter tyres on Light alloy	Bridgestone	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Storage compartment in center console with roller blind • Adaptive Highbeam Assist • Airbag for driver and front passenger • Airbag: Kneebag for driver • Airbag: Windowbag for driver and front passenger • AMG floor mats • AMG Styling • Anti-lock braking system (ABS) • Rear armrest • Left and right exterior mirrors, heated and electrically adjustable, painted in body color • Double cup holder at the front • Third brake light in LED technology • EASY-PACK tailgate • Door sills with "Mercedes-Benz" lettering • Chassis: Comfort chassis with lowered suspension • Luggage net on driver and passenger seatbacks • Transmission: 7G-DCT dual-clutch automatic transmission, 7-speed • Rear headrests (3) • Radiator grille with Mercedes-Benz pattern in chrome • Steering wheel: Multifunction sports steering wheel in Nappa leather • Navigation accessories: Pre-installation for Live Traffic Information • Package: AMG Line Advanced Plus • Package: Night (for Special Edition) • Package: Seating comfort • Package: Mirror package • Radio: Extended MBUX functions • Radio accessories: Central Media Display • Radio accessories: Communication module (LTE) for using Mercedes me connect services • Windscreen wipers with rain sensor • Seats: 4-way lumbar support for driver and front passenger • Seats: Rear seat backrests foldable, 40/20/40 split • Heated seats for driver and front passenger • Sporty engine sound • Phone accessories: Wireless charging system for mobile devices • Fully digital instrument display • Electronic immobilizer | <ul style="list-style-type: none"> • ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions • Airbag: Automatic passenger airbag deactivation • Airbag: Side airbag for driver and front passenger • Ambient lighting with 64 different colors • AMG rear apron with visible tailpipe trim and chrome trim element • Traction control (ASR) • ATTENTION ASSIST • Basic services • Brake assist, active • Tachometer • DYNAMIC SELECT • ECO start/stop function • Electronic Stability Program (ESP) • Electric windows (4-way) • Speed Limit Assistant • Black fabric headliner • THERMATIC automatic climate control • Front headrests, integrated • LED High Performance Headlights • Steering: Direct steering • Mercedes-Benz emergency call system • Navigation: MBUX Navigation Premium • Otto particulate filter • Package: Light and Visibility Package • Package: Parking package with reversing camera • Package: Special Edition • Package: USB Package Plus • Radio: MBUX multimedia system • Radio accessories: Digital radio (DAB) • Tire pressure monitoring system (TPMS) • Remote Services • Seat belts CLA-Class • Seats: i-Size child seat attachment in the rear • Seats: Front sports seats • Sport brake system • Lane Keeping Assist, active • Cruise control • TIREFIT with tire inflation compressor • High-visibility vest for drivers • Decorative elements: aluminum with longitudinal brushing, light finish |
|--|--|



Extra equipment

- Package: AMG Line Premium (ShB) (Blind Spot Assist - AMG door sills with "AMG" lettering, illuminated and with interchangeable covers - MBUX Augmented Reality for navigation - Advanced sound system - THERMOTRONIC automatic climate control - Premium Package - Parking Package with reversing camera including Active Parking Assist with PARKTRONIC - Mirror Package: electrically folding exterior mirrors, automatically dimming interior mirrors - 4-way lumbar support - Full instrument display - Wireless charging system for mobile devices in the front - KEYLESS-GO Comfort Package - Rear armrest - EASY-PACK tailgate)
- Radio accessories: Advanced sound system (with 10 speakers - midrange speaker as central speaker - one mid-bass speaker each in the front and rear doors - one tweeter each in the front doors (mirror triangles) and rear doors - one subwoofer bass box in the rear, including separate additional amplifier - maximum total power: 225 watts)
- Seats: Front right seat electrically adjustable with memory (memory programming with seat adjustment options such as height and longitudinal direction, seat cushion tilt and backrest tilt - Motion Seating with three programs and two speeds)
- Telephone accessories: Smartphone integration (wirelessly connects the mobile phone to the MBUX multimedia system - supports Android Auto and Apple CarPlay - display of selected third-party apps - access to current software and data, e.g., for navigation, traffic information, contact data, messaging, telephony, media, IP radio - optimized user interface for driving - control of smartphone functions via voice control)
- Package: Winter Package Plus with 40.6 cm (18") winter complete wheels (Winter Package - 45.7 cm (18") light alloy wheels in 5-twin-spoke design painted black and polished with 225/45 R18 on 7.5J x 18 ET49)
- Radio: MBUX multimedia system (instrument display with 17.78 cm (7") diagonal - media display with 17.78 cm (7") diagonal and touch function - touch control buttons on the steering wheel - radio (FM/AM) - USB interface in the center console under the armrest - Bluetooth telephony with contact transfer and audio streaming of music files - display of vehicle functions (driver assistance systems, driving programs and vehicle settings) - favorites storage - smartphone-related voice control)
- Wheels: 48.3 cm (19") AMG multi-spoke light-alloy wheels, painted black (aerodynamically optimized, painted black and rim flange polished with 225/40 R19 tires on 7.5J x 19 ET49 rims)
- Seats: Driver's seat electrically adjustable with memory function (memory programming with storage of the following adjustment options: height and longitudinal adjustment of the seats, adjustment of the seat cushion and seat backrest tilt, position of the exterior mirrors and the optional head-up display - dynamic seating while driving: small movements of the seat cushion and backrest in 3 programs and 2 speeds)
- Partition net for luggage compartment separation and occupant protection
- Traffic Sign Assistant

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) and the vehicle registration certificate Part 2 (title) were not available.
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - Missing - No deduction
2	Door - front left side	Door (Klebereste) - Glued / labelled - Remove
3	Sill - right side	Sill - Scratch(es) - Smart repair
4	Vehicle glazing	Windscreen (Im Sichtbereich) - Broken / torn - repair according to calculation



Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Interior - Luggage net

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Radsatz ist nicht Bestandteil der vorliegenden Fahrzeugausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres




Figure 18: Navigation




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Damage 2: Door - front left side: Door (Klebereste) - Glued / labelled - Remove



Damage 2: Door - front left side: Door (Klebereste) - Glued / labelled - Remove



Damage 3: Sill - right side: Sill - Scratch(es) - Smart repair




Damage 3: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 4: Vehicle glazing: Windscreen (Im Sichtbereich) - Broken / torn - repair according to calculation



Damage 4: Vehicle glazing: Windscreen (Im Sichtbereich) - Broken / torn - repair according to calculation



Damage 4: Vehicle glazing: Windscreen (Im Sichtbereich) - Broken / torn - repair according to calculation