



Vehicle History Report

MERCEDES GLE 350 de 4MATIC

Vehicle reference:

W1NFD1HB9PA905151

Body type:

Estate

Gearbox

type:

Automatic

Engine size:

1950 cm³

Hybrid

vehicle:

Electric,
Diesel

Combustion

engine

power:

143 kW

Drive:

AWD



Get American report!



Quick check



Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.



Import

Vehicle imported from United States

Legend



No issues reported or indicated



Valuable Information



Requires attention



Data unavailable

Damage overview


01/2025

Affected area (3):

Location reference, does not indicate the extent of the damage.

Reported in
Italy

Damage
type/cause
Not available



Left rear

Rear

Right rear

Damage severity:



Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

Owners

BETA



Owner(s) in United States

Check US history for more details on owners in United States

Technical details



Engine and performance

Hybrid vehicle

Electric, Diesel

Combustion engine power

Not available

Electric engine power

Not available

Total system power

Not available



Environment and consumption

EU emission standard

Euro 6



Other information

European vehicle category

M1

EU standard code

e1*07/46*1885*17

Number of doors

5

History information

Date	Mileage	Event
01/2023		Imported from United States to Germany
01/2025		Damage reported in Italy

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions.](#)