APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	AUDI
Model / version:	A3 SPORTBACK
Vin:	WAUZZZGY5PA045482
Plate:	2CSU811
Mileage:	100922
SOH:	
First registration:	15/11/2022
Color:	Manhattan Gr

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES




















































VIN INFORMATION

6 haut-parleurs	Téléphone	Transmission séquentielle
6 rapports	Equipement Advanced	Matière : alliage
Lettre repère (J)	Diamètre avant 17	Diamètre arrière 17
Largeur avant 8,0	Largeur arrière 8,0	Diamètre avant 17
Diamètre arrière 17	Hauteur avant 45	Hauteur arrière 45
Indice de vitesse avant V	Indice de vitesse arrière V	Largeur avant 225
Largeur arrière 225	Climatisation automatique	Climatisation réfrigérant 1234YF
Accoudoir central avant	Euro 6	Métallisée vernissée
Rétroviseur gauche asphérique	Volant cuir	Volant chauffant
Volant multifonction	Aide au stationnement avant	Aide au stationnement arrière
Assistance au parking	Caméra avant	Caméra arrière de recul

Affichage lecture des panneaux de signalisation	Appel de secours	Pare-brise teinté dégradé
Airbag passager	Airbag passager désactivable	Freinage d'urgence assistée autonome (urbain)
depuis 09.22	radio avec récepteur numérique	câble de charge pour station de recharge publique Mode 3 Type 2 (16A)
garnissage tissu Index	extincteur	1395 cc (1,4 L) 110 KW (essence) / 180 KW (Total)
205/55 R 17 .. W	système de gonflage des pneus	batterie de démarrage ar
suspension ar à 4 bras	sidebag av/ar avec airbag pour la tête et airbag central av	transmission hybride PHEV
réservoir à charbon actif (EVAP)	freins av 306x26	FREINS AR 272X10
carrosserie avec mesures de sécurité élevées		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm	Pirelli	225451794v	Winter	Aluminium	×
Front right	5 mm	Pirelli	225451794v	Winter	Aluminium	×
Rear left	5 mm	Pirelli	225451794v	Winter	Aluminium	×
Rear right	5 mm	Pirelli	225451794v	Winter	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Interior	Dirty
2	Bumper F	
2	Bumper grille FR	
3	Alloy rim FL	Scratch(es)
4	Door FL	
5	Alloy rim RL	
6	Bumper R	
7	Tailgate / Boot	Dent(s)
8	Wing RR	Damaged
8	Door RR	Damaged
9	Alloy rim RR	Scratch(es)
11	Alloy rim FR	Scratch(es)

Total: 12


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
10	Outside rear-view mirror housing R	Scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Interior - Dirty



2 - Bumper F



2 - Bumper grille FR



3 - Alloy rim FL - Scratch(es)



4 - Door FL



5 - Alloy rim RL





6 - Bumper R






7 - Tailgate / Boot - Dent(s)





8 - Wing RR - Damaged





8 - Door RR - Damaged




9 - Alloy rim RR - Scratch(es)




11 - Alloy rim FR - Scratch(es)




10 - Outside rear-view mirror housing R - Scratch(es) - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert	Customer
23/10/2026 15:53	23/10/2026 15:53
	Useless