MACADAM








Skoda Superb (KKL): 2BPS958

Vinnumber:	**TMBJW7NP6N7024366**	Versionname:	**Superb Combi Clever 1.4TSi iV 218pk/cv 5p DSG6**
First Registrationdate:	**8/02/2022**	Fiscalpower:	
Expertise Mileage:	**74623**	Power Kw:	**115**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**over 12900 km of 253 dagen**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar collapsible**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/55/17/94 V**			
	Fr.L.	**Michelin: 3 mm**	Fr.R.	**Michelin: 3 mm**
	Re.L.	**Michelin: 5 mm**	Re.R.	**Michelin: 5 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**215/55 R 17 94 V**
Tyre size FR	**215/55 R 17 94 V**
Tyre size RL	**215/55 R 17 94 V**
Tyre size RR	**215/55 R 17 94 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**1**		
Number of charging cables (rapid charge)	**1**		

Engine insulation, Tear, Replace




Windscreen, Stone chip(s), Acceptable




Step L, Scratch(es), Acceptable




Wing RR, Dent(s), Acceptable




Door RR, Scratch(es), Acceptable





Outside rear-view mirror housing R, Scratch(es), Acceptable




Door FR, Scratch(es), Acceptable




Bodywork, Not original part, Remove lettering



Onderhoudshistorie van: TMBJW7NP6N7024366

ALPHABET

Kenteken	2BPS958
Merk Model	Skoda Superb Combi Clever 1.4TSi iV 218pk/cv 5p DSG6
Brandstofsoort	Benzine
Datum deel1	2/8/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/3/26	72,434	klein materiaal	
7/3/26	72,434	koelwatervloeistof	Bijvullen/-laden
7/3/26	72,434	ruitenwisservloeistof	Bijvullen/-laden
7/3/26	72,434	Tussentijds onderhoud (vast interval)	Uitvoeren
6/27/25	61,408	bougie	Vervangen
6/27/25	61,408	klein materiaal	
6/27/25	61,408	luchtfilter interieur	Vervangen
6/27/25	61,408	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
6/27/25	61,408	remvloeistof	Vervangen
6/27/25	61,408	ruitenwisserrubber achter	Vervangen
6/27/25	61,408	ruitenwisserrubber vooraan	Vervangen
6/27/25	61,408	ruitenwisservloeistof	Bijvullen/-laden
6/27/25	61,408	versnellingsbakolie	Vervangen
10/2/24	48,662	diagnose	Uitvoeren
10/2/24	48,662	klein materiaal	Uitvoeren
10/2/24	48,662	oliefilterhuis	Vervangen
9/27/24	48,555	batterij	Vervangen
9/27/24	48,555	controle niveaus	Uitvoeren
9/27/24	48,555	olie bijvullen	Bijvullen/-laden
9/27/24	48,555	ruitenwisservloeistof	Bijvullen/-laden
7/10/23	30,364	Inspectie met olieververvanging (vast in	Uitvoeren
7/10/23	30,364	klein materiaal	Uitvoeren
7/10/23	30,364	koelwatervloeistof	Bijvullen/-laden
7/10/23	30,364	ruitenwisservloeistof	Bijvullen/-laden
11/8/22	16,456	klein materiaal	Uitvoeren
11/8/22	16,456	koelwatervloeistof	Bijvullen/-laden
11/8/22	16,456	ruitenwisservloeistof	Bijvullen/-laden
11/8/22	16,456	Tussentijds onderhoud (vast interval)	Uitvoeren