



BMW X1:

Vinnumber:	WBA71AB0305V54843	Versionname:	
First Registrationdate:	16/07/2022	Fiscalpower:	
Expertise Mileage:	106698	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1406
Fueltype:	Hybrid Petrol		
Maintenance:	NOT OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	Tow bar removable
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		
Head-up Display:			

Limited Technical Inspection

Tyres

225/50/18/99 W				
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/50 R 18 99 W
Tyre size FR				225/50 R 18 99 W
Tyre size RL				225/50 R 18 99 W
Tyre size RR				225/50 R 18 99 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Number of charging cables (normal):	1
Number of charging cables (rapid charge):	1

Total cost ex VAT	133,03
Service, Maintenance, Check	0,00



Bumper F, Scratch(es), Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Door FR, Dent(s) and scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00

