



2-EWU-624 · Move! 1.0 TSI 110cv DSG bicolor · 22 July 2026 · Zaventem (BE)

Specifications

|                      |                                 |                   |                                     |
|----------------------|---------------------------------|-------------------|-------------------------------------|
| License Plate Number | 2-EWU-624                       | Fuel Type         | Gasoline                            |
| Manufacturer         | SEAT                            | VIN               | VSSZZZKJ2RR085292                   |
| Model                | Arona                           | Cylinder Capacity | 999 <sup>cm3</sup>                  |
| Model Versions       | Move! 1.0 TSI 110cv DSG bicolor | Transmission Type | Automatisch geschakelde Transmissie |
| Body Type            | 5 door hatchback                | First Admission   | 22-02-2024                          |
| Color                | Black                           | Odometer          | 59.665 <sup>Km</sup>                |
| Paint Type           | Metallic                        | Numer Of Keys     | 2                                   |
| Production Year      | 2024                            | Interior          | Grey                                |
| KW                   | 81                              | Number Headrests  | 5                                   |

## Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

| Tire            | Profile         | Brand   | Width             | Aspect Ratio     | Radial             | Type       |
|-----------------|-----------------|---------|-------------------|------------------|--------------------|------------|
| Front Left      | 1 <sup>mm</sup> | Hankook | 205 <sup>mm</sup> | 60 <sup>mm</sup> | 16 <sup>inch</sup> | All Season |
| Rear Left       | 4 <sup>mm</sup> | Hankook | 205 <sup>mm</sup> | 60 <sup>mm</sup> | 16 <sup>inch</sup> | All Season |
| Front Right     | 1 <sup>mm</sup> | Hankook | 205 <sup>mm</sup> | 60 <sup>mm</sup> | 16 <sup>inch</sup> | All Season |
| Rear Right      | 4 <sup>mm</sup> | Hankook | 205 <sup>mm</sup> | 60 <sup>mm</sup> | 16 <sup>inch</sup> | All Season |
| Spare Tire Type | Compressor      |         |                   |                  |                    |            |

## Damages



Damage Part

Interior



Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Frontdoor - Left



Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Overfender



Damage Type

Scratch(es)

Repair Type

Replace

Acceptable

No





Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Bumper – Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Scratch(es)

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type


Acceptable

Fender – Front Right

small dents / small scratches

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor – Right

Scratch(es)

Spray

No





Damage Part  
Reardoor – Left



Damage Type  
Scratch(es)

|             |            |
|-------------|------------|
| Repair Type | Acceptable |
| Spray       | No         |



Damage Part  
Overfender



Damage Type  
Scratch(es)


|             |            |
|-------------|------------|
| Repair Type | Acceptable |
| Spray       | No         |



Damage Part  
Bumper – Rear



Damage Type  
Scratch(es)



|             |            |
|-------------|------------|
| Repair Type | Acceptable |
| Spray       | No         |