



VOLKSWAGEN GOLF SW: GQ-568-CR

Vinnumber:	VWZZZCD9PW527087	Versionname:	VOLKSWAGEN GOLF SW 2.0 TDI SCR 116 DSG LIFE PLUS SW VP [5P] bva 7-116CH-6cv (break)
First Registrationdate:	7/07/2023	Fiscalpower:	
Expertise Mileage:	157513	Power Kw:	85
Bodytype:	Break	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Roof bar black	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Other

Tyres

205/55/16/91 H				
Summer tyres:	Fr.L.	Bridgestone: 25%	Fr.R.	Bridgestone: 35%
	Re.L.	Bridgestone: 45%	Re.R.	Bridgestone: 55%
Tyre profile depth FL				6.4
Tyre profile depth FR				6.0
Tyre profile depth RL				5.4
Tyre profile depth RR				4.6
Tyre size FL				205/55 R 16 91 H
Tyre size FR				205/55 R 16 91 H
Tyre size RL				205/55 R 16 91 H
Tyre size RR				205/55 R 16 91 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Interior, Stain, Cleaning			






Alloy rim FL, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Paint



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Bumper moulding F, Broken, Replace




Bumper moulding FR, Scratch(es), Paint



Wing RR, Dent(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Paint



Outside rear-view mirror housing R, Scratch(es), Paint



Tailgate / Boot, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Rear roof pillar covering R, Scratch(es), Replace



Rear roof pillar covering L, Scratch(es), Replace



Historique Maintenance

Immatriculation: **GQ-568-CR**

Date de 1ère immatriculation: **07/07/2023**

Modèle: **Volkswagen GOLF SW 2.0 TDI SCR 116 DSG LIFE PLUS SW VP [5P] bva 7-116CH-6cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
06/11/2025	128.865	CAPISCOL DISTRIBUTION	REVISION
	0		BALAI ESSUIE GLACE AR
	0		BALAI ESSUIE GLACE AV
02/06/2025	97.073	AUDEXIA	REVISION ET CLIM
	0		LIQUIDE DE FREIN
07/11/2024	63.615	AUDEXIA	BALAI ESSUIE GLACE AV
	0		PLAQUETTES AV RPLT
	0		PILE DE CLE RPLT
22/05/2024	38.906	AUDEXIA	REVISION
	0		LIQUIDE LAVE GLACE