



SKODA Kamiq: 4168-MDZ

Vinnumber:	TMBGR6NW4P3064930	Versionname:	1.0 TSI 81kW (110CV) AMBITION todoterreno
First Registrationdate:	21/02/2023	Fiscalpower:	81kW 5P manual
Expertise Mileage:	105580	Power Kw:	
Bodytype:	SUV	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Petrol		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	1	Central consol F
Number keys remote	1	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		Roof bar alu
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

205/60/16/92 V				
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 92 V
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Registration document, Missing, Repair/replace (lump sum)



Ignition key, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Glove compartment lid, Scratch(es), Replace




Wing RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)





Door FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

