



Peugeot 3008 (UKL): 2BUD764

Vinnnumber:	VF3MCYHZUNS054011	Versionname:	3008 Allure 1.5 BlueHDi S&S 130pk/cv 5p EAT8
First Registrationdate:	24/03/2022	Fiscalpower:	
Expertise Mileage:	132878	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Diesel		
Maintenance	OK		
Maintenance	+12700 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/55/18/102 Y			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/55 R 18 102 Y
Tyre size FR				225/55 R 18 102 Y
Tyre size RL				225/55 R 18 102 Y
Tyre size RR				225/55 R 18 102 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Engine insulation, Hole, Replace



Wing FL, Scratch(es), Acceptable



Mirror side repeater L, Scratch(es), Replace



Wing FR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Acceptable



Kenteken	2BUD764
Merk Model	Peugeot 3008 Allure 1.5 BlueHdi S&S 130pk/cv 5p EAT8
Brandstofsoort	Diesel
Datum deel1	3/24/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/26/26	124,635	gloeibougie	Vervangen
2/26/26	124,635	remblokken achter	Vervangen
2/26/26	124,635	remschijven en blokken vooraan	Vervangen
11/18/25	115,648	120000 km	Uitvoeren
11/18/25	115,648	brandstof hoofdfilter	Vervangen
11/18/25	115,648	luchtfilter	Vervangen
11/18/25	115,648	luchtfilter interieur	Vervangen
11/18/25	115,648	oliezeef	Vervangen
1/30/25	92,414	90000 km	Uitvoeren
1/30/25	92,414	oliezeef	Vervangen
6/19/24	70,964	75000 km	Uitvoeren
6/19/24	70,964	oliezeef	Vervangen
11/10/23	47,755	50000 km	Uitvoeren
11/10/23	47,755	brandstof hoofdfilter	Vervangen
11/10/23	47,755	luchtfilter	Vervangen
11/10/23	47,755	luchtfilter interieur	Vervangen
11/10/23	47,755	oliezeef	Vervangen
11/10/23	47,755	ruitenswisserrubber vooraan	Vervangen
3/7/23	25,719	25000 km	Uitvoeren
3/7/23	25,719	oliezeef	Vervangen