MACADAM









Polestar 2: R258KR

Vinnumber:	**YSMVSEGE4PL118161**	Versionname:	**Polestar 2 170kW/ 78kWh Single Motor Long Range**
First Registrationdate:	**25/10/2022**	Fiscalpower:	
Expertise Mileage:	**138765**	Power Kw:	**170**
Bodytype:		Body colour	**Void**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**349**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Panoramic roof	
GPS		Rear parking sensors	
Autom climate control		Hook	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 108 / V / Aluminium	5,0 mm	Michelin	Summer
	Right	245 / 45 / 19 / 108 / V / Aluminium	5,0 mm	Michelin	Summer
Rear	Left	245 / 45 / 19 / 108 / V / Aluminium	6,0 mm	Michelin	Summer
	Right	245 / 45 / 19 / 108 / V / Aluminium	5,0 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Service, Maintenance, Execute



Wing RL, Dent(s), Repair and paint (complete)




Roof pillar L, Dent(s), Repair and paint (complete)





Wing RR, Scratch(es), Repair and paint (complete)






Door FR, Dent(s), Paintless dent repair



Bumper R, Scratch(es), Repair and paint (complete)







Onderhoudshistorie van: YSMVSEGE4PL118161

ALPHABET

Kenteken	R258KR
Merk Model	Polestar Polestar 2 170kW/ 78kWh Single Motor Long Range
Brandstofsoort	Elektrisch
Datum deel1	10/25/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
9/11/26	132,969	APK
1/21/26	112,924	High Voltage batterij
1/21/26	112,924	Sleutelbatterij
4/4/25	100,749	Onderhoudsbeurt
9/3/24	78,407	Onderhoudsbeurt
9/3/24	78,407	Ruitenwisserblad(en) voorzijde
9/3/24	78,407	Vervanging band
3/6/24	58,271	Onderhoudsbeurt
3/6/24	58,271	Remvloeistof
11/15/22	1,382	High Voltage lader aansluiting