CARFAX Vehicle History Report

LAND ROVER Range Rover Evoque

Vehicle reference:

SALVA2BN4HH215426

Body type:
Estate

Gearbox type:
Automatic

Engine size:
1999 cm³

Fuel type:
Diesel

Combustion engine power:
110 kW / 150 hp

Drive:
AWD

CO2 emissions in mixed driving:
134 g/km



Quick Check

Damage
This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

Damage

Import
Not a private import

No issues reported

Located in Italy




Vehicle age
9 years
2 months

1-Owner vehicle



Damage Overview

03/2024 Damage reported



Affected area:

- Right
- Right rear

Severity scale:

Minor

Damage type/cause:


Not available

Reported on:

03/2024

Reported in:

Italy




Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

Mileage Check

Date	Mileage
2021-02-16	55 040 km



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Owners BETA



Owner 1 in Italy	
Purchase year:	**2017**
Length of use:	**9 years 2 months**
Damage reported on:	**03/2024**

History information

Date	Mileage	Event
2017-02-01		Registered in Italy New owner reported
2021-02-16	55 040 km	Inspected in Italy
03/2024		Damage reported in Italy

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

Technical details

Engine and performance	
Fuel type	**Diesel**
Combustion engine power	**110 kW / 150 hp**
Environment and consumption	
Fuel consumption in mixed driving	**5.1 l/100km**
CO2 emissions in mixed driving	**134 g/km**
EU emission standard	**Euro 6**
Weight	
Curb weight	**1 860 kg**
Max payload	**490 kg**
Gross vehicle weight	**2 350 kg**
Dimensions	
Length	**4 360 mm**
Width	**1 900 mm**
Wheelbase	**2 660 mm**
Other information	
European vehicle category	**M1**
EU standard code	**e11*2007/46*0223*17**
Number of doors	**5**
Number of seats	**5**

CARFAX Glossary

1-Owner vehicle

1-Owner vehicle has been only used by one owner and consequently comes with the advantage that only one owner is responsible for its use

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick Check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our Terms and conditions.