Peugeot

VIN: VR3FCYHZTMY551329

Estimated repair cost

49.00 EUR
TOTAL



Description

Registration number	First registration date	Odometer
2EUM263	-	81032 km
Color	**Model year**	**Upholstery**
-	-	-
Number of doors	**Number of seats**	**Generation**
-	-	-

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction	net cost
001	Door / Front Left Material : Metal / Windowed : Yes	Dent	Smart repair	49.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**49.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

#	Element	Defect	Correction	net cost
002	Door / Back Right Material : Metal / Windowed : Yes	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

Loose Items

- [x] Tyre repair kit complete
- [x] Triangle
- [x] User manual
- [x] Service book
- [x] Compressor tyre repair kit
- [x] First aid kit
- [x] Rear parcel shelf
- [x] Registration certificate
- [x] Document holder
- [x] Registration certificate owner
- [x] Refill tyre repair kit
- [x] Spare Key

Main set of tyres

Front Left	HANKOOK	215/60/16 99 V All-season	5 mm
Front Right	HANKOOK	215/60/16 99 V All-season	5 mm
Back Left	HANKOOK	215/60/16 99 V All-season	6 mm
Back Right	HANKOOK	215/60/16 99 V All-season	6 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right


Odometer


Spare Tyre



Vin


Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door / Front Left / Dent



Door / Front Left / Dent



Door / Front Left / Dent



Door / Back Right / Dent



Door / Back Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.