

## 2-DNZ-193

2-DNZ-193 · ST-line 125pk 92kw mHEV M6 5d · 22 June 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-DNZ-193	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0NXXGCHNPL84026
Model	Focus	Cylinder Capacity	999 <sup>cm<sup>3</sup></sup>
Model Versions	ST-line 125pk 92kw mHEV M6 5d	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	10-05-2023
Color	Blue	Odometer	77.882 <sup>Km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	92	Number Headrests	5

# Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 <sup>mm</sup>	Goodyear	215 <sup>mm</sup>	50 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Left	6 <sup>mm</sup>	Goodyear	215 <sup>mm</sup>	50 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Front Right	4 <sup>mm</sup>	Goodyear	215 <sup>mm</sup>	50 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Right	6 <sup>mm</sup>	Goodyear	215 <sup>mm</sup>	50 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Spare Tire Type	Compressor					

## Damages



Damage Part

Frontdoor - Left

Damage Type

small dents / small scratches

Repair Type

Restyle / Touch-up

Acceptable

No



Damage Part

Alloy - Left Rear

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Alloy - Left Front

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

small dents / small scratches

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Front

Damaged

Rim repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Front Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

Scratch(es)

Spray

No



Damage Part

spoiler RB

Damage Type

Damaged

Repair Type

Spotrepair

Acceptable

No



Damage Part

Bumper - Rear

Damage Type

Small scratch(es)

Repair Type

Touch-up / Polish

Acceptable

No



Damage Part

Rear seat

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No