



Volkswagen Tiguan (KKL): 2CFR938

Vinnnumber:	WVGZZZ5NZNM090664	Versionname:	Tiguan Allspace Life 1.5TSi 150pk/cv 5p DSG7
First Registrationdate:	6/07/2022	Fiscalpower:	
Expertise Mileage:	137762	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:	Petrol		
Maintenance	NOT OK		
Maintenance	sinds 4400km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/55/18/104 H			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				7.0
Tyre profile depth RR				6.0
Tyre size FL				235/55 R 18 104 H
Tyre size FR				235/55 R 18 104 H
Tyre size RL				235/55 R 18 104 V
Tyre size RR				235/55 R 18 104 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				2477
Tyre make RR				2477

Assistance equipment

MOT certificate, Non-conforme, Replace



Service, Maintenance, Check



Floor covering FL, Hole, Replace



Seat cover FL, Damaged, Replace



Interior, Smell, Ozone treatment



Door panel RL, Scratch(es), Smart repair



Seat cover RL, Hole, Replace



Interior, Dirty, Cleaning



Roof liner, Damaged, Replace



Engine insulation, Damaged, Replace



Bumper F, Scratch(es), Acceptable



Step L, Dent(s), Repair and paint (complete)



Step L, Scratch(es), Acceptable



Door FL, Dent(s), Paintless dent repair



Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Smart repair



Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Paintless dent repair



Wing FR, Dent(s), Paintless dent repair



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Paintless dent repair



Step R, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Kenteken	2CFR938
Merk Model	Volkswagen Tiguan Allspace Life 1.5TSi 150pk/cv 5p DSG7
Brandstofsoort	Benzine
Datum deel1	7/6/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/25/25	101,000	Inspectie met olie vervanging (vast in	Uitvoeren
8/25/25	101,000	klein materiaal	
8/25/25	101,000	luchtfilter	Vervangen
8/25/25	101,000	luchtfilter interieur	Vervangen
8/25/25	101,000	ruitenwisserrubber achter	Vervangen
8/25/25	101,000	ruitenwisserrubber vooraan	Vervangen
8/25/25	101,000	ruitenwisservloeistof	Bijvullen/-laden
8/25/25	101,000	waterafvoer open dak	Reinigen
10/22/24	68,964	bougie	Vervangen
10/22/24	68,964	klein materiaal	Uitvoeren
10/22/24	68,964	luchtfilter interieur	Vervangen
10/22/24	68,964	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
10/22/24	68,964	remblokken achter	Vervangen
10/22/24	68,964	remblokken vooraan	Vervangen
10/22/24	68,964	remvloeistof	Vervangen
11/20/23	30,211	Inspectie met olie vervanging (vast in	Uitvoeren
11/20/23	30,211	klein materiaal	
11/20/23	30,211	ruitenwisserrubber achter	Vervangen
11/20/23	30,211	ruitenwisserrubber vooraan	Vervangen
11/20/23	30,211	waterafvoer open dak	Reinigen
3/3/23	13,346	controle niveaus	Uitvoeren
3/3/23	13,346	klein materiaal	Uitvoeren
3/3/23	13,346	olie bijvullen	Uitvoeren
3/3/23	13,346	ruitenwisserrubber vooraan	Vervangen
3/3/23	13,346	ruitenwisservloeistof	Bijvullen/-laden