



RENAULT KANGOO: GF-576-SE

Vinnumber:	VF1RFK00867690306	Versionname:	RENAULT KANGOO EXTRA - BLUE DCI 95 SÅ%O SAME
First Registrationdate:	7/04/2022		OUVRE TOI VU [4P] bvm 6-95CH-5cv
Expertise Mileage:	177432		(fourgonnettesimple cabine)
Bodytype:	Transporter	Fiscalpower:	70
Gearbox:	MAN 5 VIT	Power Kw:	White
Transmission:	Front	Body colour	Opaque
Fueltype:	Diesel	Paint type	Black
Engine functioning	Yes	Interior colour	Steel
Battery functioning	Yes	Type of rims (mounted)	Black
Vehicle running	Yes	Dashboard color	
Number of doors	5		
Number of seats	2		
Number head rests	2		
Type of rims (mounted)	Steel		
Category	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Rear parking sensors	
GPS big screen color		Sliding door right-side	
Windows electric F		Rear view camera	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Type of climate control	Manual climate control		

Tyres

	205/60/16/96 H			
Summer tyres:	Fr.L.	Other: 75%	Fr.R.	Other: 60%
	Re.L.	Other: 55%	Re.R.	Other: 60%
Tyre profile depth FL				3.5
Tyre profile depth FR				4.3
Tyre profile depth RL				4.7
Tyre profile depth RR				4.4
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				263
Tyre make FR				263
Tyre make RL				263
Tyre make RR				263

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Seat cover FR, Stain, Cleaning



Seat cover FL, Tear, Replace



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Side panel L, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Acceptable



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing FR, Scratch(es), Acceptable



Bumper R, Hole, Repair and paint (complete)



Rubber seal for boot lid, Tear, Replace



Boot door lining L, Broken, Replace



Bodywork, Not original part, Sticker removal small

