



CITROËN BERLINGO: FL-563-NC

Vinnumber:	VR7EFYHYCKJ812047	Versionname:	CITROËN BERLINGO M 650kg BlueHDi 100 BVM
First Registrationdate:	13/11/2019		Driver VU [4P] bvm 5-100CH-5cv
Expertise Mileage:	71239		(fourgonnettesimple cabine)
Bodytype:	Transporter	Fiscalpower:	73
Gearbox:	MAN 5 VIT	Power Kw:	White
Transmission:	Front	Body colour:	Metallic
Fueltype:	Diesel	Paint type:	Black
Engine functioning:	Yes	Interior colour:	Steel
Battery functioning:	Yes	Type of rims (mounted):	Black
Vehicle running:	Yes	Dashboard color:	
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Front parking sensors	
GPS big screen color		Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Type of climate control	Manual climate control		

Tyres

	195/65/15/95 V			
Summer tyres:	Fr.L.	Michelin: 60%	Fr.R.	Michelin: 60%
	Re.L.	Michelin: 50%	Re.R.	Michelin: 50%
Tyre profile depth FL				4.3
Tyre profile depth FR				4.4
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/65 R 15 95 V
Tyre size FR				195/65 R 15 95 V
Tyre size RL				195/65 R 15 95 V
Tyre size RR				195/65 R 15 95 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Remote ignition key, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Tyre RL, Flat, Acceptable



Tyre FR, Tear, Replace



Side wall RL, Dent(s), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Paint



Sliding door R, Scratch(es), Polish



Boot door panel RL, Adjust, Adjust



Bodywork, Glue residues, Sticker removal small



Historique Maintenance

Immatriculation: **FL-563-NC** Date de 1ère immatriculation: **13/11/2019**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
27/04/2026	67.387	MECACAR	RECYCLAGE
	0		RESERVOIR ADBLUE RPLT
24/03/2026	66.117	MECACAR	RECYCLAGE
	0		PLAQUETTES AR RPLT
	0		REVISION
14/01/2026	59.403	MECACAR	POT CATALYTIQUE FAP RPLT
29/10/2025	56.079	MECACAR	RECYCLAGE
	0		DIVERS CARROSSERIE
25/07/2025	49.332	MECACAR	LAMPE CODE AVD RPLT
	0		RECYCLAGE
	0		ECLAIRAGE DE PLAQUE RPLT
23/05/2025	45.609	MECACAR	DIVERS CLIM
	0		REVISION
	0		FILTRE CLIM RPLT
	0		COURROIE ACCESSOIRES RPLT
	0		PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
16/04/2025	44.418	MECACAR	RECYCLAGE
	0		LAMPE CODE AVD RPLT
08/01/2025	36.826	MECACAR	ECLAIRAGE DE PLAQUE RPLT
	0		LIQUIDE LAVE GLACE
07/12/2023	30.276	AUTOMOBILE PREMIUM FONTAINE	REVISION
	0		BALAIS ESSUIE GLACE AV
	0		DIVERS CLIM
	0		REVISION
	0		FILTRE A AIR RPLT
	0		LIQUIDE DE FREIN
	0		FILTRE CLIM RPLT
	0		RECYCLAGE
22/12/2022	24.455	EUROMASTER FRANCE	REMPLACEMENT PNEUS HIVER
11/01/2022	19.058	FRANCE PARE BRISE SAS	CUSTODE ARD RPLT

Historique Maintenance

Immatriculation: **FL-563-NC**

Date de 1ère immatriculation: **13/11/2019**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 BVM Driver VU [4P] bvm 5-100CH-5cv
(fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
13/09/2021	16.553	GARAGE DU SONNANT	LIQUIDE DE FREIN
	0		REVISION
	0		FILTRE CLIM RPLT
04/12/2020	10.242	FRANCE PARE BRISE SAS	VITRE AVD RPLT
09/07/2020	746	EUROMASTER FRANCE	GARDIENNAGE
	0		REMPLACEMENT PNEUS HIVER