MACADAM










Volkswagen Caddy: VRN67V

Vinnumber:	**WV1ZZZSK1PX007384**	Versionname:	**Caddy 1.5 TSI 98kW CNG Maxi (o.v. voor PostNL-Post) klant-spec.**
First Registrationdate:	**21/09/2022**	Fiscalpower:	
Expertise Mileage:	**155270**	Power Kw:	**98**
Bodytype:		Body colour	**Candy white**
Gearbox:	**MAN 6 VIT**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Steel**
Fueltype:	**Petrol**	Parking lot	**976**
Number of seats	**2**		
Type of rims (mounted)	**Steel**		
Maintenance needed	**Yes**		

Options

Number of keys total	**1**	Rear parking sensors	
Manual climate control		Sliding door right-side	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 17 / 98 / H / Steel	3,8 mm	Continental	All season
	Right	215 / 55 / 17 / 98 / H / Steel	4,8 mm	Continental	All season
Rear	Left	215 / 55 / 17 / 98 / W / Steel	4,7 mm	Bridgestone	All season
	Right	215 / 55 / 17 / 98 / W / Steel	4,5 mm	Bridgestone	All season

Assistance equipment

Service, Maintenance, Execute



Interior, Dirty, Chemical cleaning





Wing FL, Scratch(es), Repair and paint (complete)




Door FL, Scratch(es), Polish





Outer sill L, Dent(s), Repair and paint (complete)




Bonnet, Scratch(es), Repair and paint (complete)




Bumper FL, Scratch(es), Smart repair



Brand badge F, Missing, Replace



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)






Door FR, Scratch(es), Repair and paint (complete)




Seat, Worn, Replace




Ignition key, Missing, Replace

No pictures to display

Onderhoudshistorie van: WV1ZZZSK1PX007384

ALPHABET

Kenteken	VRN67V
Merk Model	Volkswagen Caddy 1.5 TSI 98kW CNG Maxi (o.v. PostNL-Post) klantspec.
Brandstofsoort	CNG
Datum deel1	9/21/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
6/2/26	144,201	APK
6/2/26	144,201	Bougie
6/2/26	144,201	Onderhoudsbeurt
6/2/26	144,201	Remschijf + blokken achter
6/2/26	144,201	Remschijf + blokken voor
6/2/26	144,201	Ruitenwisserblad(en) voorzijde
6/2/26	144,201	Vervanging band
4/8/26	140,759	Vervanging band
3/19/26	138,788	Reparatie band(en)
1/16/26	132,843	Vervanging band
10/3/25	123,062	APK
10/3/25	123,062	CNG-tank keuring
10/3/25	123,062	Onderhoudsbeurt
10/3/25	123,062	Remblokken achterzijde
8/29/25	119,275	Dynamo
4/3/25	105,495	Vervanging band
3/21/25	104,414	Onderhoudsbeurt
3/13/25	103,051	Vervanging band
1/17/25	96,483	Luchtfilter
1/17/25	96,483	Onderhoudsbeurt
1/17/25	96,483	Remschijf + blokken voor
11/13/24	88,583	Bougie
11/13/24	88,583	Onderhoudsbeurt
11/13/24	88,583	Remblokken achterzijde
11/13/24	88,583	Remvloeistof
11/13/24	88,583	Vervanging band
8/15/24	77,445	Reparatie band(en)
7/11/24	73,146	Remschijf exclusief blokken achter
5/1/24	64,216	Onderhoudsbeurt
5/1/24	64,216	Remblokken voorzijde
5/1/24	64,216	Ruitenwisserblad(en) voorzijde
1/3/24	48,525	Bougie
1/3/24	48,525	Onderhoudsbeurt
1/3/24	48,525	Remschijf + blokken achter
1/3/24	48,525	Vervanging band
8/23/23	31,264	Onderhoudsbeurt
8/23/23	31,264	Remblokken achterzijde
8/23/23	31,264	Remblokken voorzijde
8/23/23	31,264	Ruitenwisserblad(en) voorzijde
7/14/23	25,790	Vervanging band

Datum reparatie	Kilometerstand	Reparatie omschrijving
7/5/23	24,732	Vervanging band
3/27/23	16,743	Onderhoudsbeurt
12/29/22	8,700	Reparatie band(en)
12/13/22	6,947	Vervanging band