



Volkswagen TRANSPORTER 2.0TDI 150pk 7-DSG L2H1 32 Comfortline Exec. Plus LED Park, Nov-20, 178,785 km



Memo



VIN	WV1ZZZ7HZMH015146
Initial registration	20-11-2020
Initial Dutch Registration	20-11-2020
European Type Approval	e1*2007/46*0130*37
Mileage reading / hour counter reading	178,785 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	Diesel
Cylinders / Engine capacity	4 / 1968
Weight	1913 kg
Doors	5
Power capacity	110 kW
Emission code / Energy label	6
Wheelbase	340
Loading space	
Load capacity	1287
RDW details	
Battery capacity	
Range	
Battery health	
Charging cables type	
AC/DC	
Battery purchase/rent	Unknown
Taxation	VAT (Grey number plate)
Colour	Gray
Country of registration	The Netherlands
Origin	Lease

Accessories fitted to vehicles

 Manually operated air conditioning	 Electric windows front	 Sliding door right
 ABS	 LED lighting	 Start immobiliser
 Bluetooth telephone connection	 Metallic paint	 Tow bar
 Central locking remote control	 Navigation	 Heated mirrors
 Cruise control	 Parking sensors rear	
 Electronic Stability Program	 Parking sensors front + rear	

Accessories fitted to vehicles (stated by offerer, conditionally)

- Achterklep
- Airco
- Armsteun voor
- Bestuurdersairbag
- Bluetooth telefoonvoorb.
- Boordcomputer
- Buitensp. elektr. verst.
- Comfortstoel(en)
- ESD
- ESP
- Hill hold functie
- Lendesteunen (verstelb.)
- Multimedia-voorbereiding
- Passagiersairbag
- Start/stop systeem
- Vermoeidheids herkenning
- Verstelbaar stuur
- Vervolgbotsing preventie
- Zijschuifdeur rechts
- Zijwind assistent



Comments

No remarks

Vehicle state

MOT due date	02-08-2026	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location Owner	Wheel locks	Not present



Tyres

Rim size	16"		
Wheel	Brand	Type	Tread depth
Front wheel left	Continental	Summer tyre	6 mm
Front wheel right	Continental	Summer tyre	4 mm
Rear wheel left	Continental	Summer tyre	8 mm

Rear wheel right	Continental	Summer tyre	5 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			
Bodywork inspection			
Incident	Component	Observations	
Unacceptable damage			
1		Interior	dirt (interior)
2		Interior	smoke odor
3		Engine bonnet	various damage (see photo)
4		Front door right	various damage (see photo)
5		Schuifdeur r	dent(s)
6		Rear door right	dent(s)
7		Rear door left	various damage (see photo)
			
8		Koetswerk	Niet origineel
Comments			
No remarks			
Vendor			