



## Tesla Model Y

Vinnnumber:	LRWYGCEK4NC255747	Versionname:	
First Registrationdate:	15/03/2022	Fiscalpower:	
Expertise Mileage:	81024	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3422
Fueltype:	Electric		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

## Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Panoramic roof:	
Seats F heated:		Rear parking sensors:	
Radio multimedia:		Type of Tow bar:	No Tow bar
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

## Limited Technical Inspection

## Tyres

255/45/19/104 Y				
Summer tyres:	Fr.L.	Semperit: 8 mm	Fr.R.	Semperit: 8 mm
	Re.L.	Semperit: 8 mm	Re.R.	Semperit: 8 mm
Tyre profile depth FL				8.0
Tyre profile depth FR				8.0
Tyre profile depth RL				8.0
Tyre profile depth RR				8.0
Tyre size FL				255/45 R 19 104 Y
Tyre size FR				255/45 R 19 104 Y
Tyre size RL				255/45 R 19 104 Y
Tyre size RR				255/45 R 19 104 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				2477
Tyre make RR				2477

## Assistance equipment

Number of charging cables (normal):	1
Number of charging cables (rapid charge):	1

Total cost ex VAT	583,07
Bumper F, Scratch(es), Acceptable	0,00



Windscreen, Repaired, Acceptable 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Alloy rim RL, Scratch(es), Repair and paint (complete) 133,03



Wing RL, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Internal boot lining R, Scratch(es), Acceptable 0,00



Internal boot lining L, Scratch(es), Acceptable 0,00



Boot lid covering R, Scratch(es), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



Wheel cover RR, Scratch(es), Replace 50,95





Door RR, Dent(s) and scratch(es), Repair and paint (complete) 0,00



Wing trim RR, Scratch(es), Replace 0,00



Sill trim R, Scratch(es), Acceptable 0,00



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00

