



BMW X1 (UKL): 2BSA073

Vinnumber:	WBA31AC0X05V12084	Versionname:	X1 (F48) 16d sDrive 1.5d 116pk/cv 5p Aut.
First Registrationdate:	2/03/2022	Fiscalpower:	
Expertise Mileage:	40190	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	7000.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/17/97 W				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				3.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/55 R 17 97 W
Tyre size FR				225/55 R 17 97 W
Tyre size RL				225/55 R 17 97 W
Tyre size RR				225/55 R 17 97 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Seat cover FL, Worn, Acceptable



Bumper F, Scratch(es), Spot repair



Bumper moulding F, Scratch(es), Smart repair



Door FL, Scratch(es), Acceptable



Wing trim FL, Scratch(es), Smart repair



Alloy rim RL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Door FR, Dent(s), Acceptable



Kenteken	2BSA073
Merk Model	BMW X1 (F48) 16d sDrive 1.5d 116pk/cv 5p Aut.
Brandstofsoort	Diesel
Datum deel1	3/2/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
8/29/25	32,775	batterij	Vervangen
8/29/25	32,775	BMW/MINI service standaard omvang	Uitvoeren
8/29/25	32,775	ruitenswisserrubber vooraan	Vervangen
8/29/25	32,775	service microfilter	Uitvoeren
8/29/25	32,775	service motorolie	Uitvoeren
1/6/25	28,185	BMW/MINI service standaard omvang	Uitvoeren
1/6/25	28,185	remblokken vooraan	Vervangen
1/6/25	28,185	ruitenswisserrubber achter	Vervangen
1/6/25	28,185	ruitenswisserrubber vooraan	Vervangen
10/31/23	16,814	BMW/MINI service standaard omvang	Uitvoeren
10/31/23	16,814	klein materiaal	
10/31/23	16,814	service microfilter	Uitvoeren
10/31/23	16,814	service motorolie	Uitvoeren