



**Skoda Superb:**

Vinnnumber:	<b>TMBJN7NPXN7045532</b>	Versionname:	
First Registrationdate:	<b>18/05/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>116497</b>	Power Kw:	
Bodytype:		Body colour:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3633</b>
Fueltype:	<b>Petrol</b>		
Maintenance:	<b>OK</b>		
Maintenance:	<b>22100.0</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Seats electric F L:	
Cruise Control:		Luggage cover:	
Steering wheel multifunctional:		Front parking sensors:	
Seats F heated:		Rear parking sensors:	
Type of headlighting:	<b>Headlighting LED</b>	Type of Tow bar:	<b>Tow bar collapsible</b>
Type of GPS:	<b>GPS big screen color</b>		
Type of Lining:	<b>Lining fabrics</b>		
Type of climate control:	<b>Autom climate control</b>		
Sport seats:			
Type of GPS storage:	<b>HD</b>		

**Limited Technical Inspection**

**Tyres**

<b>235/45/18/98 V</b>				
Winter tyres:	Fr.L.	<b>Pirelli: 7 mm</b>	Fr.R.	<b>Pirelli: 7 mm</b>
	Re.L.	<b>Vredestein: 5 mm</b>	Re.R.	<b>Vredestein: 5 mm</b>
Tyre profile depth FL				<b>7.0</b>
Tyre profile depth FR				<b>7.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>235/45 R 18 98 V</b>
Tyre size FR				<b>235/45 R 18 98 V</b>
Tyre size RL				<b>235/45 R 18 98 V</b>
Tyre size RR				<b>235/45 R 18 98 V</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>264</b>
Tyre make FR				<b>264</b>
Tyre make RL				<b>2480</b>
Tyre make RR				<b>2480</b>

**Assistance equipment**

Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Number of charging cables (normal):	<b>0</b>		
Number of charging cables (rapid charge):	<b>0</b>		

Total cost ex VAT	<b>361,53</b>
Windscreen, Stone chip(s), Acceptable	<b>0,00</b>



Bumper F, Scratch(es), Acceptable 0,00




Door FL, Dent(s), Paintless dent repair 95,47



Step L, Scratch(es), Acceptable 0,00



Alloy rim FL, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Door FL, Dent(s), Acceptable 0,00



Door trim FL, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Bumper moulding R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Internal boot lining R, Broken, Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00



Alloy rim RR, Scratch(es), Repair and paint (complete) 133,03



Alloy rim FR, Scratch(es), Repair and paint (complete) 133,03

