

2-EUM-869

2-EUM-869 · Move! 1.0 TSI 110cv DSG bicolor · 30 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-EUM-869	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ4RR084256
Model	Arona	Cylinder Capacity	999 ^{cm³}
Model Versions	Move! 1.0 TSI 110cv DSG bicolor	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	01-02-2024
Color	Black	Odometer	49.563 ^{km}
Paint Type	Metallic	Numer Of Keys	1
Production Year	2024	Interior	Grey
KW	81	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	2 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Hankook	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Fender - Rear Left

Damage Type

small dents / small scratches

Repair Type

Restyle / Polish

Acceptable

No



Damage Part

Reardoor - Left

Damage Type

Small scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Frontdoor - Left

Damage Type

Door-edge chipped

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Mirror - Rightside

Previous Repair

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Rear

Scratch(es)

Spray

No



Damage Part

Interior



Damage Type

Stains & dirt



Repair Type

Cleaning

Acceptable

No