



RENAULT TRAFIC: FH-192-FM

Vinnumber:	VF1FL000561426107	Versionname:	RENAULT TRAFIC FG GCF L1H1 1000 Energy dCi 125
First Registrationdate:	25/06/2019		E6 VU [4P] bvm 6-125CH-5cv (fourgon tA
Expertise Mileage:	116092		1A@simple cabine)
Bodytype:	Transporter	Fiscalpower:	92
Gearbox:	MAN 6 VIT	Power Kw:	White
Transmission:	Front	Body colour:	Opaque
Fueltype:	Diesel	Paint type:	Black
Engine functioning:	Yes	Interior colour:	Steel
Battery functioning:	Yes	Type of rims (mounted):	Steel
Vehicle running:	Yes	Dashboard color:	Black
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Headlights Xenon/LED/Laser	
GPS big screen color		Rear parking sensors	
GPS storage		Roof rack	
GPS storage	HD	Sliding door right-side	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Steering wheel multifunctional			
Type of climate control	Manual climate control		

Tyres

	205/66/16/105 T			
Summer tyres:	Fr.L.	Bridgestone: 75%	Fr.R.	Bridgestone: 75%
	Re.L.	Bridgestone: 35%	Re.R.	Bridgestone: 50%
Tyre profile depth FL				3.4
Tyre profile depth FR				3.4
Tyre profile depth RL				6.0
Tyre profile depth RR				4.9
Tyre size FL				205/66 R 16 105 T
Tyre size FR				205/66 R 16 105 T
Tyre size RL				205/66 R 16 105 T
Tyre size RR				205/66 R 16 105 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Spare wheel	No	Jack	No
Remote ignition key, Missing, Repair/replace (lump sum)			



Seat cover FL, Burned, Replace



Interior, Dirty, Cleaning



Door panel FR, Scratch(es), Replace



Tyre FR, Out of tolerance, Replace



Tyre FL, Out of tolerance, Replace



Wheel cover RR, Scratch(es), Acceptable



Wheel cover RL, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Side panel L, Scratch(es), Acceptable



Bumper moulding F, Deformed / Strained, Replace



Headlight L, Scratch(es), Polish



Bumper grille, Unclasp(ed), Dismount/Mount



Bumper F, Scratch(es), Polish



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s), Repair and paint (complete)



Door trim RR, Scratch(es), Replace



Car body corner RR, Scratch(es), Polish



Jack, Missing, Repair/replace (lump sum)



Rubber seal for boot lid, Tear, Replace



Bumper R, Deformed / Strained, Repair and paint (complete)



Boot door panel RR, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RL, Dent(s), Repair and paint (complete)



Bodywork, Not original part, Sticker removal small



Load compartment roof, Dent(s), Repair and paint (complete)



Historique Maintenance

Immatriculation: FH-192-FM Date de 1ère immatriculation: 25/06/2019

Modèle: Renault TRAFIC FG GCF L1H1 1000 Energy dCi 125 E6 VU [4P] bvm 6-125CH-5cv (fourgon tôle simple cabine)

Date	Kilométrage	Fournisseur	Descriptif
10/04/2026	115.282	GARAGE VERHAEGHE SARL	ADBLUE
	0		LIQUIDE DE REFROIDISSEMENT RPLT
	0		KIT ACCESSOIRES RPLT
	0		REVISION ET CLIM
16/05/2025	99.968	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
07/08/2024	79.337	GARAGE ASLOUN LILLE	ANTIPOLLUTION
08/02/2024	70.808	GARAGE ASLOUN LILLE	LIQUIDE DE FREIN
	0		REVISION
	0		REVISION
	0		FILTRE A AIR RPLT
	0		BATTERIE RPLT
	0		CEINTURE DE SECURITE RPLT
19/06/2023	59.394	GARAGE ASLOUN LILLE	CONTROLE TECHNIQUE
15/11/2022	48.681	NOUVEAUX GARAGES LILLOIS	REVISION ET CLIM
	0		ADBLUE
	0		PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		RECYCLAGE
	0		PLAQUETTES AR RPLT
08/09/2022	44.598	NORAUTO SAS (PRODUIT SPE)	REMPLACEMENT PNEUS ETE
23/08/2021	26.223	GARAGE ASLOUN LILLE	ADBLUE
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV