MACADAM









VOLKSWAGEN T-CROSS: GB-306-SE

Vinnumber:	**WVGZZZC1ZMY151820**	Versionname:	**VOLKSWAGEN T-CROSS 1.0 TSI 110ch DSG Lounge Business VP [5P] bva 7-110CH-6cv (SUV)**
First Registrationdate:	**10/09/2021**	Fiscalpower:	
Expertise Mileage:	**159088**	Power Kw:	**81**
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Petrol**	Type of rims (mounted)	**Aluminium**
Engine functioning	**No**	Dashboard color	**Black**
Battery functioning	**No**		
Vehicle running	**No**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**1**	Radio	
Number keys remote	**1**	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Front parking sensors	
GPS storage	**HD**	Rear parking sensors	
Windows electric F		Roof bar black	
Windows electric R		Seat cover lining	**Lining Other**
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	**Manual climate control**		

Tyres

Winter tyres:	**205/60/16/96 H**			
	Fr.L.	**Bridgestone: 85%**	Fr.R.	**Bridgestone: 75%**
	Re.L.	**Bridgestone: 50%**	Re.R.	**Bridgestone: 70%**

Tyre profile depth FL	**2.3**
Tyre profile depth FR	**3.5**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**3.7**
Tyre size FL	**205/60 R 16 96 H**
Tyre size FR	**205/60 R 16 96 H**
Tyre size RL	**205/60 R 16 96 H**
Tyre size RR	**205/60 R 16 96 H**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Emergency spare wheel	**Yes**	Jack	**Yes**

Interior covering B pillar R, Scratch(es), Replace





Interior, Dirty, Cleaning







Seat cover FL, Burned, Replace




Remote ignition key, Missing, Repair/replace (lump sum)



Tyre FR, Out of tolerance, Replace






Alloy rim FR, Scratch(es), Acceptable





Tyre RR, Out of tolerance, Replace






Tyre FL, Out of tolerance, Replace







Tyre RL, Out of tolerance, Replace





Wing FL, Dent(s), Repair and paint (complete)




Door RL, Scratch(es), Acceptable




Bumper F, Scratch(es), Paint




Bumper moulding F, Scratch(es), Replace






Bumper moulding FR, Scratch(es), Replace




Bumper spoiler F, Scratch(es), Paint





Wing RR, Dent(s), Acceptable




Door RR, Scratch(es), Paint




Wing trim RR, Scratch(es), Replace




Door FR, Dent(s) and scratch(es), Repair and paint (complete)








Wing FR, Chemical polution, Polish




Bumper R, Deformed / Strained, Replace




Bumper R, Scratch(es), Paint







Tailgate / Boot, Not functioning (well), Check



ALPHABET

Historique Maintenance

Immatriculation: **GB-306-SE** Date de 1ère immatriculation: **10/09/2021**

Modèle: **Volkswagen T-CROSS 1.0 TSI 110ch DSG Lounge Business VP [5P] bva 7-110CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
11/02/2026	144.245	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
31/10/2025	135.143	EUROFLEET TYRES AND SERVICES	GARDIENNAGE
	0		PERMUTATIONS PNEUS
16/10/2025	133.400	CENTRAL AUTOS	DISQUES PLAQUETTES AV RPLT
	0		REVISION
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		LIQUIDE DE FREIN
14/05/2025	117.426	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
09/12/2024	102.350	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
09/10/2024	96.258	CENTRAL AUTOS	REVISION
	0		PLAQUETTES AR RPLT
15/05/2024	84.918	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
06/11/2023	70.046	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER
06/09/2023	64.575	CENTRAL AUTOS	PLAQUETTES AV RPLT
	0		REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
13/07/2023	58.109	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
30/11/2022	35.237	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
28/09/2022	30.836	CENTRAL AUTOS	REVISION ET CLIM
	0		REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV AR
	0		BALAIS ESSUIE GLACE AV AR
16/06/2022	20.798	EUROFLEET TYRES AND SERVICES	PERMUTATIONS PNEUS
	0		GARDIENNAGE
02/11/2021	1.103	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS HIVER

Historique Maintenance

Immatriculation: **GB-306-SE** Date de 1ère immatriculation: **10/09/2021**

Modèle: **Volkswagen T-CROSS 1.0 TSI 110ch DSG Lounge Business VP [5P] bva 7-110CH-6cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
	0		GARDIENNAGE