

Vehicle

License Plate		Contract Number		Bodywork Type	SUV	Transmission	Automatic
Brand	HYUNDAI	VIN	TMAJD81BHMJ049084	Drive Wheel	Front-wheel-drive	First Registration	2021.09.16
Model	Tucson	Year Built	2021	Color	White	Fuel Type	Hybrid
Label	-	Capacity	1.598 cm3	Power	132 kW	Mileage	63.115 km
MOT	2027.11.14						

Equipment

- Automatic air conditioning / digital
- Electrically adjustable front and rear windows
- Multifunction steering wheel
- ESP / DSC
- ASD / EDS / ASR
- Navigation

Documents

- Original Key
- Registration Book
- Tyre Repair Kit

Wheels

Position	Rim Type	Dimensions	Thread Depth
FL	Könnyűfém	235/55R18	5.00
FR	Könnyűfém	235/55R18	5.00
RL	Könnyűfém	235/55R18	5.00
RR	Könnyűfém	235/55R18	5.00

Paint Thickness [µm]

Part	Left Value	Right Value
Front mudguard	210	112
Engine cover	138	0
Front door	123	129
Rear door	135	127
Roof	127	0
Rear mudguard	122	132
Luggage compartment lid / Rear door	151	0

Last Service

Type	Date	KM
------	------	----

Standard Images





Unacceptable Damage

Csomagtérfedél

Part	Csomagtérfedél	Damage	Stone impact	Repair Method	Painting

Bal hátsó ajtó

Part	Bal hátsó ajtó	Damage	Dented	Repair Method	Painting and Repairment

Bal első küszöb

Part	Bal első küszöb	Damage	Scratched	Repair Method	Painting

Fényezett elemek

		No images or videos available.			
Part	Fényezett elemek	Damage		Repair Method	Preparation and painting

Special Notes

This condition report was prepared by an expert of DEKRA-Expert Kft.
The vehicle inspection was carried out by external visual examination. No test drive was performed and no parts were disassembled during the inspection.
The calculation of unacceptable defects and deficiencies was prepared using data from the Audatex and Eurotax calculation programs.
The expert inspection was carried out in accordance with DEKRA regulations, applying the client's guidelines regarding acceptable and unacceptable defects and deficiencies for returned vehicles.