


DEKRA Automotive Solutions

Vehicle details

VIN	YSMVSEGE7 PL111155	Registration date	01/01/1900	Exterior Color	Unknown
Brand	Polestar	Licence Plate	2FPP443	Odometer	94 528 km
Model	2				

Inspection Details

Arrival Date	29/06/2026	Inspection ID	7049322	Inspection date	09/07/2026
Assign Date	29/06/2026	Fleet owner	LIZY Belgique	Inspection loc.	Parc Lizy



Generic equipment

Removable element

Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓
Spare key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Hankook 245/45/19 Y All seasons 5.0 mm		Hankook 245/45/19 Y All seasons 5.0 mm	
Hankook 245/45/19 Y All seasons 5.0 mm		Hankook 245/45/19 Y All seasons 5.0 mm	

Damages

1



Part	Special rim 19"	Repair Time	-	Part Cost	-
Position	Front left	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	Net Cost	-

DEKRA Automotive Solutions

2		Part	Special rim 19"	Repair Time	-	Part Cost	-
		Position	Back left	Repair Cost	-	Gross Cost	225.00€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Smart Repair	Flat Rate	225.00€	Net Cost	225.00€
3		Part	Bumper	Repair Time	0.50	Part Cost	-
		Position	Back right	Repair Cost	37.50€	Gross Cost	37.50€
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Polishing	Flat Rate	37.50€	Net Cost	37.50€
4		Part	Special rim 19"	Repair Time	-	Part Cost	-
		Position	Back right	Repair Cost	-	Gross Cost	-
		Damages	Rusty	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Under Warranty	Flat Rate	-	Net Cost	-
5		Part	Bumper	Repair Time	-	Part Cost	-
		Position	Front right	Repair Cost	-	Gross Cost	-
		Damages	Scratched	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-
		sous reserve					

Summary Inspection

Gross Price	262.50€	Depreciation	-	Net Price	262.50€
-------------	---------	--------------	---	-----------	---------

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	75.00€	0.50	37.50€	-	-	37.50€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	0.00€	-	-	0.00€
Flat Rate	225.00€	-	-	225.00€

Signatures

Signature Receiver

Signature Expert

Signature Customer / Driver

ADB Interior srl



09-07-26 08:48