



Peugeot Rifter: 2CQG222

Vinnumber:	VR3ERHNP2NJ760449	Versionname:	Rifter Standard Allure 1.2 PureTech S/S 110pk/cv
First Registrationdate:	17/10/2022	Fiscalpower:	5p
Expertise Mileage:	107123	Power Kw:	81
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/65/16/107 T				
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				215/65 R 16 107 T
Tyre size FR				215/65 R 16 107 T
Tyre size RL				215/65 R 16 107 T
Tyre size RR				215/65 R 16 107 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	No	Compressor	No
------------	----	------------	----

Bonnet, Chemical pollution, Acceptable



Bumper moulding F, Scratch(es), Acceptable



Engine, Not functioning (well), Check



Windscreen, Repaired, Acceptable



Door RL, Chemical polution, Acceptable



Door FL, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Compressor, Missing, Replace



Tyre repair kit, Missing, Replace



Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering



Kenteken	2CQG222
Merk Model	Peugeot Rifter Standard Allure 1.2 PureTech S/S 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	10/17/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/17/26	104,391	Technische Indicatie	Uitvoeren
4/15/26	104,391	diagnose	Uitvoeren
4/15/26	104,391	olie bijvullen	Bijvullen/-laden
3/17/26	100,363	controle niveaus	Uitvoeren
1/15/26	99,882	diagnose	Uitvoeren
1/15/26	99,882	lambda sonde	Vervangen
1/15/26	99,882	testrit	Uitvoeren
12/1/25	97,892	diagnose	Uitvoeren
12/1/25	97,892	injector	Vervangen
12/1/25	97,892	testrit	Uitvoeren
10/29/25	97,890	100000 km	Uitvoeren
10/29/25	97,890	oliezeef	Vervangen
10/29/25	97,890	remblokken vooraan	Vervangen
10/9/25	96,680	riem of multiriem	Vervangen
6/19/25	90,237	universele lampen	Vervangen
9/16/24	78,133	bougie	Vervangen
9/16/24	78,133	oliezeef	Reinigen
8/21/24	77,179	controle niveaus	Uitvoeren
4/23/24	61,749	60000 km	Uitvoeren
4/23/24	61,749	oliezeef	Vervangen
9/6/23	38,670	40000 km	Uitvoeren
9/6/23	38,670	bougie	Vervangen
9/6/23	38,670	luchtfILTER	Vervangen
9/6/23	38,670	luchtfILTER interieur	Vervangen
9/6/23	38,670	oliezeef	Vervangen
4/14/23	21,150	20000 km	Uitvoeren
4/14/23	21,150	oliezeef	Vervangen