VEHICLE REPORT

IT · 11/11/2026
2026-11-11 13:54

VIN: Targa: Merchant:

VEHICLE DETAILS

Targa		First Registration	**2019-07-23**
Marca	N/A	Mileage	N/A
Modello e Allestimento		Keys	N/A
VIN		Owners	**10**
Merchant		Seats	**4**
Branch		Previous Use	**AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE**
KW	**331**	VAT	N/A
CC	**0**	Country	**IT**
Fuel	**BENZ**	Euro	**EURO6**
GPL	**Non presente**	Cambio	**Non presente**
Gancio	N/A		

CAR PHOTOS (36)


Rear fender left



Speedometer with started engine


Interior front


Center console and dashboard


Center console and dashboard


Center console and dashboard



Center console and dashboard


Center console and dashboard


Interior front


Center console and dashboard


Interior front


Center console and dashboard


Interior front.


Engine compartment


Hood


Interior front.


Interior rear


Hood


Hood


Hood


Front fender left


Additional photos (optional)


Additional photos (optional)


Trunk



Trunk


Rear



Rear fender left


Rear


Left side rear


Front left


Front


Front


Rear fender left


Trunk


Hood


Trunk

CARFAX **Vehicle History Report**

2020 PORSCHE 911

Vehicle reference:
WP0ZZZ99ZLS218123

Body type:
Coupe

Engine size:
2981 cm³

Total system power:
331 kW / 450 hp

Combustion engine power:
331 kW / 450 hp

Gearbox type:
Automatic

Fuel type:
Petrol

Quick check

Damage
Total loss reported

Import
Not a private import

Legend

- No issues reported or indicated
- Valuable Information
- Requires attention
- Data unavailable

Damage overview

10/2020

Affected area



Reported in
Italy

Damage type/cause
Total loss

Estimated repair cost:


€ 82,000 - € 83,000

This is a rough estimate and the actual repair cost may be higher or lower. It does not show whether the damage has already been repaired. Prices are based on local rates and can vary between countries.

01/2021

Affected area (5):

Location reference, does not indicate the extent of the damage.



- Front
- Left
- Left front
- Rear
- Right front

Reported in
Italy

Damage type/cause
Not available

Damage severity:


Moderate

Functional damage to one or more components, may impair vehicle operation and/or safety.

06/2022

Affected area (8):

Location reference, does not indicate the extent of the damage.



- Front
- Left
- Left front
- Left rear
- Rear
- Right
- Right front
- Right rear

Reported in
Italy

Damage type/cause
Not available

Damage severity:

Moderate

Functional damage to one or more components, may impair vehicle operation and/or safety.

Damage Glossary

Total loss

A vehicle is declared a total loss by the insurance company when the cost of repairs exceeds a significant percentage (typically 60–80%, depending on the insurer) of its value before the damage. Even if the vehicle has sustained significant damage, it could still be repairable, rebuilt to meet safety standards and driven again.

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

Recommended maintenance

Default schedule
Provided by CARFAX Europe



Vehicle age
7 years, 3 months

Maintenance due so far

These service tasks are expected based on the vehicle age. Verify if they were completed.

Before buying, ask the seller:
- Are service records available?
- Were the following services performed?

Engine oil and oil filter **due 7 times**
Change every year

Brake fluid **due 3 times**
Change every 2 years

Costly upcoming service tasks

Before buying, confirm whether:
- Any of the upcoming maintenance tasks are already completed.
- You've accounted for related costs in your future budget.

Brake discs and pads
Inspect yearly, replace as needed

Tires
Inspect yearly, replace as needed

CARFAX tips



Keeping up with scheduled servicing is a strong indicator that the vehicle has been well cared for and is in good overall condition.

Mileage Check

No issues reported

According to the data provided to CARFAX, there are no indications of odometer manipulation.

Last odometer reading


48 401 km

Reported on: 2025-09-13

Today's mileage projection

For this vehicle

~58 111 km



CARFAX tips



Mileage can have a significant impact on a vehicle's value.

Consider whether the mileage matches what you'd expect for the vehicle. Look for signs of wear, compare the readings with typical yearly averages.

Owners BETA



Owner 1 in Italy

Purchase year:
2019

Length of use:
1 year 3 months

Type of owner:
Commercial business

Damage reported on:
10/2020

Owner 2 in Italy

Purchase year:
2020

Length of use:
1 month

Type of owner:
Commercial business

Owner 3 in Italy

Purchase year:
2021

Length of use:
1 year 5 months

Type of owner:
Commercial business

Damage reported on:
01/2021

Owner 4 in Italy

Purchase year:
2022

Length of use:
7 months

Type of owner:
Commercial business

Damage reported on:
06/2022

Owner 5 in Italy

Purchase year:
2023

Length of use:
1 year 9 months

Type of owner:
Commercial business

Owner 6 in Italy

Purchase year:
2024

Length of use:
less than a month

Type of owner:
Commercial business

Owner 7 in Italy

Purchase year:
2024

Length of use:
less than a month

Type of owner:
Private individual

Owner 8 in Italy

Purchase year:
2024

Length of use:
2 months

Type of owner:
Commercial business

Owner 9 in Italy

Purchase year:
2025

Type of owner:
Private individual

Technical details

Engine and performance

Fuel type
Petrol

Combustion engine power
331 kW / 450 hp

Environment and consumption

CO2 emissions in mixed driving
206 g/km 

Fuel consumption in mixed driving
9.0 l/100km

EU emission standard
Euro 6

Weight

Curb weight
1 640 kg

Max payload
370 kg

Gross vehicle weight
2 010 kg

Dimensions

Length
4 519 mm

Width
1 852 mm

Height
1 300 mm

Wheelbase
2 450 mm

Other information

European vehicle category
M1

Number of doors
2

Number of seats
4

History information

Date	Mileage	Event
2019-07-23		**Registered in Italy** New owner reported Owner type: commercial
10/2020		**Total loss reported in Italy**
10/2020	7 675 km	**Offered for sale in EU country**
2020-11-19		**New owner reported** Owner type: commercial
2021-01-08		**New owner reported** Owner type: commercial
01/2021		**Damage reported in Italy**
2022-06-09		**New owner reported** Owner type: commercial
06/2022		**Damage reported in Italy**
2023-01-11		**Leasing reported**

		New owner reported Owner type: commercial
2024-10-24		**New owner reported** Owner type: commercial
2024-10-29		**New owner reported** Owner type: private individual
2024-11-08		**New owner reported** Owner type: commercial
2025-01-17		**New owner reported** Owner type: private individual
2025-09-13	48 401 km	**Inspected in Italy** Inspection passed Inspection valid until 2027-09-30

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our Terms and conditions.