



BMW X3:

Vinnumber:	WBATS110X09G13279	Versionname:	xDrive30e (120 kW)
First Registrationdate:	6/04/2021	Fiscalpower:	
Expertise Mileage:	163932	Power Kw:	120
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3821
Fueltype:	Hybrid Petrol		
Maintenance	NOT OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar collapsible
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/60/18/104 H				
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL	4.0			
Tyre profile depth FR	4.0			
Tyre profile depth RL	4.0			
Tyre profile depth RR	4.0			
Tyre size FL	225/60 R 18 104 H			
Tyre size FR	225/60 R 18 104 H			
Tyre size RL	225/60 R 18 104 H			
Tyre size RR	225/60 R 18 104 H			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	259			
Tyre make FR	259			
Tyre make RL	259			
Tyre make RR	259			

Assistance equipment

Number of charging cables (normal)	0	
Number of charging cables (rapid charge)	1	
Total cost ex VAT		95,47
Service, Maintenance, Check		0,00



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Wing trim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wing FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Charging cable (normal), Missing, Check	0,00
---	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Door FR, Dent(s), Painless dent repair	95,47
--	-------



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------

