VEHICLE REPORT

Estero · 09/11/2026
2026-11-09 16:46

VIN: Targa: Merchant:

VEHICLE DETAILS

Targa		First Registration	**2017**
Marca	N/A	Mileage	N/A
Modello e Allestimento		Keys	N/A
VIN		Owners	**9**
Merchant		Seats	**4**
Branch		Previous Use	**AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE**
KW	**310**	VAT	N/A
CC	**0**	Country	**Estero**
Fuel	**GASOL**	Euro	**EURO6C**
GPL	**Non presente**	Cambio	**Non presente**
Gancio	N/A		

CAR PHOTOS (62)


Front left


Speedometer with started engine


Left side front


Front left


Interior front


Trunk


Center console and dashboard


Interior front


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Left side rear



Left side front


Left side front


Left side front


Left side rear


Underbody view.


Left side front.


Rear fender left


Center console and dashboard


Center console and dashboard


Center console and dashboard


Interior front


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Front left



Front



Front left



Rear



Rear



Front left



Front left



Rear fender left



Rear fender left



Left side front



Center console and dashboard



Interior front



Rear.



Interior front



Hood



Additional photos (optional)



Left side front



Front left



Rear



Rear



Roof



Left side rear



Interior rear.



Interior rear.



Interior rear.



Interior rear.



Interior front.



Interior front



Rear



Left side front



Engine compartment



Engine compartment



Engine compartment

CARFAX Vehicle History Report

2017 PORSCHE PANAMERA

Vehicle reference:
WP0ZZZ97ZHL130995

Body type:
Hatchback

Engine size:
2967 cm³

Total system power:
221 kW / 300 hp

Combustion engine power:
221 kW / 300 hp

Gearbox type:
Automatic

Fuel type:
Diesel

Quick check

Damage
This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

Import
Not a private import

Legend


- No issues reported or indicated
- Valuable Information
- Requires attention
- Data unavailable

Damage overview

2018-04-17

Affected area (1):

Location reference, does not indicate the extent of the damage.



Front

Reported in
Romania

Damage type/cause
Not available

Affected components (1):

Windshield / Glass

Estimated repair cost:


RON 4,000 - RON 5,000

This is a rough estimate and the actual repair cost may be higher or lower. It does not show whether the damage has already been repaired. Prices are based on local rates and can vary between countries.

07/2019

Affected area (3):

Location reference, does not indicate the extent of the damage.



Rear
Right
Right rear

Reported in
Italy

Damage type/cause
Not available

Damage severity:


Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

10/2022

Affected area (8):

Location reference, does not indicate the extent of the damage.



- Front
- Left
- Left front
- Left rear
- Rear
- Right
- Right front
- Right rear

Reported in
Italy

Damage type/cause
Vandalism

Damage severity:


Moderate

Functional damage to one or more components, may impair vehicle operation and/or safety.

09/2024

Affected area (8):

Location reference, does not indicate the extent of the damage.



- Front
- Left
- Left front
- Left rear
- Rear
- Right
- Right front
- Right rear

Reported in
Italy

Damage type/cause
Vandalism

Damage severity:

Moderate

Functional damage to one or more components, may impair vehicle operation and/or safety.

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

Recommended maintenance

Default schedule
Provided by CARFAX Europe

Vehicle age
9 years, 4 months

Maintenance due so far

These service tasks are expected based on the vehicle age. Verify if they were completed.

Before buying, ask the seller:

- Are service records available?
- Were the following services performed?

Engine oil and oil filter **due 9 times**
Change every year

Brake fluid **due 4 times**
Change every 2 years

Diesel fuel filter **due 4 times**
Change every 2 years

Costly upcoming service tasks

Before buying, confirm whether:

- Any of the upcoming maintenance tasks are already completed.
- You've accounted for related costs in your future budget.

Brake discs and pads
Inspect yearly, replace as needed

Tires
Inspect yearly, replace as needed

CARFAX tips

Keeping up with scheduled servicing is a strong indicator that the vehicle has been well cared for and is in good overall condition.

Mileage Check

No issues reported

According to the data provided to CARFAX, there are no indications of odometer manipulation.

Last odometer reading

167 657 km


Reported on: 2022-11-21

Today's mileage projection

For this vehicle

~327 217 km

Date	Mileage projection
2026-11-10	~327 217 km



CARFAX tips



Mileage can have a significant impact on a vehicle's value.

Consider whether the mileage matches what you'd expect for the vehicle. Look for signs of wear, compare the readings with typical yearly averages.

Owners BETA



Owner(s) in Italy

Purchase year:
2017

Damage reported on:
2018-04-17

Owner(s) in Italy

Purchase year:
2019

Damage reported on:
07/2019

Owner(s) in Italy

Purchase year:
2021

Damage reported on:
09/2024 , 10/2022

Technical details

Engine and performance

Fuel type
Diesel

Combustion engine power
221 kW / 300 hp

Environment and consumption

CO2 emissions in mixed driving
169 g/km 

Fuel consumption in mixed driving
6.4 l/100km

EU emission standard
Euro 5

Weight

Gross vehicle weight
2 500 kg

Other information

European vehicle category
M1

Number of doors
5

Number of seats
4

History information

Date	Mileage	Event

07/2017		**Registered in Italy**
2018-04-17		**Damage reported in Romania**
04/2018	25 000 km	**Odometer reading reported**
2019-02-12		**Registered in Italy**
07/2019		**Damage reported in Italy**
2021-10-28		**New owner reported**
2022-02-11	133 869 km	**Inspected in Italy**
10/2022		**Damage reported in Italy caused by vandalism**
11/2022	167 657 km	**Odometer reading reported**
2024-03-29		**Inspected in Italy**
09/2024		**Damage reported in Italy caused by vandalism**

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

CO2 Emissions

CO2 is an abbreviation for carbon dioxide, a gas that is emitted from a vehicle as a result of fuel combustion. The quantity of carbon dioxide released in the exhaust gases is a good measure of the amount of fuel a car is burning. That quantity is measured by the number of grams of CO2 released into the air for every kilometer that is driven.

Model year

This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our Terms and conditions.